Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 Support : | **W** : www.vallabhenterprises.com **E** : vallabhsecure@yahoo.co.in

Service Status Details : VE8577 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9833008982 **No. : Technician Name** Kalpesh Subhash Gurav **Technician Mobile :** 8879684054 Complain 14-06-2023 02:04:33 **Ticket Type : Date & Time :** Vendor Details : Brijkutir Bldg Customer's Mobile : 9833008982 Rajan Bhai Company Name : Name/Client Name Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** CCTV Flat no. 91 - intercom off issue, Flat no. 61- intercom need to start **Complain**: 91 Required Telephone Instrument 61 The customer does not have a phone 187 Main Gate Line Technician **Comment** : OK Complain Desktop - Apurva Vajaria **Operator** : **Remark** : 91 Required Telephone Instrument 61 The customer does not have a phone 187 Main Gate Line OK **Status History : Date Time Technician Name** Status Remark Sign 14-06-2023 Kalpesh SubhashGurav Completed 91 Required Telephone 05:08:58 Instrument 61 The customer does not have a phone 187 Main Gate Line OK 14-06-2023 Kalpesh SubhashGurav New 02:04:40 Previous **Date Time Technician Name** Remark **Complain History** 09-06-2023 11:27:37 Kalpesh SubhashGurav Out Gate Intercom Problem Solved Main Gate Intercom Cable Faulty 10-05-2023 02:51:09 Kalpesh SubhashGurav The cable of the intercom is broken, a new cable has to be installed. The temporary line is switched on.