Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE13335 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 8169144587 **No. :** Technician Rahul Mhapralkar **Technician Mobile** 9168762949 Name : Complain 22-11-2024 12:50:01 **Ticket Type : Date & Time : Vendor Details : Corporate Square** Customer's Mobile 8169144587 Rajendra Sir Company Name : Name/Client Ghatkopar Name : Address : Mumbai,,,400076, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** CCTV **Complain**: 10th floor camera need to change and some access card need to add 10th floor camera installation work done, now working normally. Access reader pressing button Technician **Comment** : issue taken for repair 2 device for Identix company. Complain Desktop - Apurva Vajaria **Operator** : **Remark** : 10th floor camera installation work done, now working normally. Access reader pressing button issue taken for repair 2 device for Identix company. **Status History : Date Time Technician Name** Status Remark Sign 22-11-2024 Rahul Mhapralkar Completed 10th floor camera installation 05:31:54 work done, now working normally. Access reader pressing button issue taken for repair 2 device for Identix company. 22-11-2024 Rahul Mhapralkar New 12:50:09 Previous **Date Time Technician Name** Remark Complain 09-12-2024 12:12:47 ChandanYadav dvr hdd disk abnormal and hdd format and dvr recording **History** : start. dvr is a under observation. 14-10-2024 01:02:58 Rahul Mhapralkar CCTV & ACCESS PPM DONE 1 NO DVR RECORDING ISSUE RESOLVED, 10TH FLOOR CAMERA FAULTY. 3RD FLOOR CAMERA BNC CONNECTOR CHANGE.