## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

E: vallabhsecure@y							
Service Status D	Details: VE1920						
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	8169144587						
Technician Name :	Neeraj Chauhan		Techn:	ician Mobile 8898885764			
Ticket Type :	Complain	Date & Time :	29-09	-2020 11:13:02			
Vendor Details :	-		-				
Company Name/Client Name :	Corporate Square Ghatkopar	Customer's Mod	oile 81691	44587	Name :	Rajendra Sir	
Address:							
Mumbai , , , 400	0076 , Maharashtra						
AMC Details:	_						
Expiry Date :	01-01-1970 05:30:0	00	Type:	Type:			
Product Name:	CCTV						
Complain:	Need to do 3 dvr online Check location of access control system						
Technician Comment :	3 dvr online done ivms 4500 1)DVR IP = 192.168.0.200 2)DVR IP =192.168.0.201 3) DVR IP = 192.168.0.203 static ip = 103.131.93.47 all dvr password =admin /admin@123 3 Mobile access ivms 4500 loclay view reception pc and door access survey done and work done						
Complain Operator :	Desktop - Apurva Vajaria						
Remark :	3 dvr online done ivms 4500 1)DVR IP = 192.168.0.200 2)DVR IP =192.168.0.201 3) DVR IP = 192.168.0.203 static ip = 103.131.93.47 all dvr password =admin /admin@123 3 Mobile access ivms 4500 loclay view reception pc and door access survey done and work done						
Status History :	Date Time	Technician Name	Status	R	emark	Sign	
	01-10-2020 01:18:34	Neeraj Chauhan	Completed	IP = 192.168.0.201 =192.168.0.201 192.168.0.203 s 103.131.93.47 a =admin /admin(ivms 4500 loclay	3) DVR IP = tatic ip =	ess	
	29-09-2020 11:13:27	Neeraj Chauhan	New			-	
	29-09-2020 11:13:02	Neeraj Chauhan	New			-	

Previous Complain History :	Date Time	Technician Name	Remark
	27-07-2023 03:28:07	Kalpesh SubhashGurav	DVR No.3 10th floor camera Faulty DVR no3 16 number port issue Lift camera issue Pending Required Lift technician DVR to lobby TV 100 meter CAT 6 cable Required Lobby access (identx) not working properly HDMI splitter 3 in1out Required. hdmi to rj 45 converter Required
	16-05-2023 09:57:14	Atique Salmani	Ther is wire cut by mouse so rejoint 8 core wire and also coverd by 25 mm flexible pipe and also reset date n time and add 1 security person finger .all completed.