

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE6293																																			
Priority :	Low																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	8169144587																																		
Technician Name :	Yogesh Desai	Technician Mobile :	8080922963																																
Ticket Type :	New Installation	Date & Time :	02-09-2022 03:49:20																																
Vendor Details :																																			
Company Name/Client Name :	Corporate Square Ghatkopar	Customer's Mobile :	8169144587	Name :	Rajendra Sir																														
Address :																																			
Mumbai , , , 400076 , Maharashtra																																			
AMC Details :																																			
Expiry Date :	01-01-1970 05:30:00		Type :																																
Product Name :	CCTV																																		
Complain :	4 camera install with cabling																																		
Technician Comment :																																			
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :																																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>23-09-2022 10:06:40</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr><tr><td>22-09-2022 02:43:36</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr><tr><td>03-09-2022 10:49:53</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr><tr><td>02-09-2022 03:49:35</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr><tr><td>02-09-2022 03:49:20</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	23-09-2022 10:06:40	YogeshDesai	New		-	22-09-2022 02:43:36	YogeshDesai	New		-	03-09-2022 10:49:53	YogeshDesai	New		-	02-09-2022 03:49:35	YogeshDesai	New		-	02-09-2022 03:49:20	YogeshDesai	New		-
Date Time	Technician Name	Status	Remark	Sign																															
23-09-2022 10:06:40	YogeshDesai	New		-																															
22-09-2022 02:43:36	YogeshDesai	New		-																															
03-09-2022 10:49:53	YogeshDesai	New		-																															
02-09-2022 03:49:35	YogeshDesai	New		-																															
02-09-2022 03:49:20	YogeshDesai	New		-																															
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>27-07-2023 03:28:07</td><td>Kalpesh SubhashGurav</td><td>DVR No.3 10th floor camera Faulty DVR no3 16 number port issue Lift camera issue Pending Required Lift technician DVR to lobby TV 100 meter CAT 6 cable Required Lobby access (identx) not working properly HDMI splitter 3 in1out Required. hdmi to rj 45 converter Required</td></tr><tr><td>16-05-2023 09:57:14</td><td>Atique Salmani</td><td>Ther is wire cut by mouse so rejoin 8 core wire and also covered by 25 mm flexible pipe and also reset date n time and add 1 security person finger .all completed.</td></tr></tbody></table>					Date Time	Technician Name	Remark	27-07-2023 03:28:07	Kalpesh SubhashGurav	DVR No.3 10th floor camera Faulty DVR no3 16 number port issue Lift camera issue Pending Required Lift technician DVR to lobby TV 100 meter CAT 6 cable Required Lobby access (identx) not working properly HDMI splitter 3 in1out Required. hdmi to rj 45 converter Required	16-05-2023 09:57:14	Atique Salmani	Ther is wire cut by mouse so rejoin 8 core wire and also covered by 25 mm flexible pipe and also reset date n time and add 1 security person finger .all completed.																					
Date Time	Technician Name	Remark																																	
27-07-2023 03:28:07	Kalpesh SubhashGurav	DVR No.3 10th floor camera Faulty DVR no3 16 number port issue Lift camera issue Pending Required Lift technician DVR to lobby TV 100 meter CAT 6 cable Required Lobby access (identx) not working properly HDMI splitter 3 in1out Required. hdmi to rj 45 converter Required																																	
16-05-2023 09:57:14	Atique Salmani	Ther is wire cut by mouse so rejoin 8 core wire and also covered by 25 mm flexible pipe and also reset date n time and add 1 security person finger .all completed.																																	