Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE944 **Priority** : High **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 8169144587 **No. : Technician Name** Yasin Shaikh **Technician Mobile** 8689802313 Complain Date & Time : 20-01-2020 02:07:47 **Ticket Type : Vendor Details :** Corporate Customer's Mobile 8169144587 Rajendra Sir Company Name : Name/Client Name Square Ghatkopar Address : Mumbai,,,400076, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** CCTV **Complain**: cameras off 230 Power Point not working islive power supply band & all camera working ok Technician **Comment** : Complain Desktop - Apurva Vajaria **Operator** : **Remark** : 230 Power Point not working islive power supply band & all camera working ok **Status History : Technician Name Date Time** Status Remark Sign 20-01-2020 03:07:57 YasinShaikh Completed 230 Power Point not working isliye power supply band & all Atte camera working ok 20-01-2020 02:07:55 YasinShaikh New 20-01-2020 02:07:48 YasinShaikh New Previous **Date Time Technician Name** Remark **Complain History** 27-07-2023 Kalpesh DVR No.3 10th floor camera Faulty DVR no3 16 number 03:28:07 SubhashGurav port issue Lift camera issue Pending Required Lift technician DVR to lobby TV 100 meter CAT 6 cable Required Lobby access (identx) not working properly HDMI splitter 3 in1out Required. hdmi to rj 45 converter Required 16-05-2023 Atique Salmani Ther is wire cut by mouse so rejoint 8 core wire and also 09:57:14 coverd by 25 mm flexible pipe and also reset date n time and add 1 security person finger .all completed.