Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Details : Priority : Low	VE10393					
Priority: Lov						
11101109 1	Low					
Created By: Adr	Admin - Apurva Vajaria					
Complaint Mob. 986	9869439970					
Technician Name Ra	Ravi Rajbhar		Technician N	Mobile 8080922965		
Ticket Type : Con	mplain D	ate & Time :	27-12-2023 03:05:47			
Vendor Details :	•					
Company Ed Name/Client Name :	en Garden C:	ustomer's Mobile	9869439970	Nam	e:	Rajesh Sir
Address :					-	
Mumbai , , , , Maharash	tra					
AMC Details :						
Expiry Date : 01	01-01-1970 05:30:00		Type:			
Product Name : CC	CCTV					
Complain: gro	ground floor a wing and b wing camera need to install					
	b wing lobby camera change and old camera remove and take to office and lobby camera WDR on in cmaera					
Complain Des Operator :	Desktop - Apurva Vajaria					
	b wing lobby camera change and old camera remove and take to office and lobby camera WDR on in cmaera					
Status History :	Date Time	Technician Nam	e Status	Rema	rk	Sign
1	5-01-2024 12:29:40	Ravi Rajbhar	Completed	b wing lobby ca change and old remove and tak and lobby came on in cmaera	camera se to office	MIMINE
1	5-01-2024 11:25:55	Ravi Rajbhar	New			-
1	2-01-2024 11:41:20	Ravi Rajbhar	New			-
Previous	Date Time	Technician Name	Remark			
Complain History :	1-02-2024 10:50:19	Siddhesh Chavan	1)b wing lift lobby phone keypad work ok 2) b wing lift no 1 line working ok phone ok 3) a wibg lift 1 line ok phone issue 4) main gate phone side rj11 used and line working ok			
ı I 	0-01-2024 04:25:17	PravinJagade	Lobby area phone working and lift line ok but phone falty.			