

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE11367															
Priority :	Low														
Created By :	Admin - Apurva Vajaria														
Complaint Mob. No. :	9820007487														
Technician Name :			Technician Mobile :												
Ticket Type :	New Installation	Date & Time :	12-04-2024 02:47:40												
Vendor Details :															
Company Name/Client Name :	Shanti Apt	Customer's Mobile :	9820007487	Name :	Rajesh Sir										
Address :															
Mumbai , , , Maharashtra															
AMC Details :															
Expiry Date :	01-01-1970 05:30:00		Type :												
Product Name :	CCTV														
Complain :	Shanti f wing Need to do a survey n install access														
Technician Comment :															
Complain Operator :	Desktop - Apurva Vajaria														
Remark :															
Status History :	<table><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr><tr><td>01-01-1970 05:30:00</td><td></td><td></td><td></td><td>-</td></tr></table>					Date Time	Technician Name	Status	Remark	Sign	01-01-1970 05:30:00				-
	Date Time	Technician Name	Status	Remark	Sign										
01-01-1970 05:30:00				-											
Previous Complain History :	<table><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr><tr><td>13-11-2024 03:16:20</td><td></td><td></td></tr><tr><td>07-11-2024 10:54:44</td><td>ManojPolekar</td><td>F wing ppm done, change the CMOS battery.one camera lift not working and chek the office.lock problem solve. Intercom ppm done. Office dvr ppm done.</td></tr></table>					Date Time	Technician Name	Remark	13-11-2024 03:16:20			07-11-2024 10:54:44	ManojPolekar	F wing ppm done, change the CMOS battery.one camera lift not working and chek the office.lock problem solve. Intercom ppm done. Office dvr ppm done.	
	Date Time	Technician Name	Remark												
	13-11-2024 03:16:20														
07-11-2024 10:54:44	ManojPolekar	F wing ppm done, change the CMOS battery.one camera lift not working and chek the office.lock problem solve. Intercom ppm done. Office dvr ppm done.													