Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Details : VE11436								
Priority:	Low							
Created By:	Admin - Apurva Vajaria							
Complaint Mob. No. :	9869439970							
Technician Name:	Atique Salmani		Technician Mobile :	8080922984				
Ticket Type :	Complain	Date & Time:	23-04-2024 12:43:05					
Vendor Details :								
Company Name/Client Name :	Eden Garden	Customer's Mobile :	9869439970	Name:	Rajesh Sir			
Address:								
Mumbai , , , , Maharashtra								
AMC Details :								
Expiry Date :	01-01-1970 05:30:00		Type:					
Product Name:	CCTV							
Complain:	B-1202 camera need to shift but angle require same							
Technician Comment :	Camera can installed same location but after work.							
Complain Operator :	Desktop - Apurva Vajaria							
Remark:	Camera can installed same location but after work.							

Status History :	Date Time	Technician Name	Status	Remark	Sign
	24-04-2024 12:22:22	Atique Salmani	Client Side	Camera can installed same location but after work.	MIN
	24-04-2024 12:22:20	Atique Salmani	Client Side	Camera can installed same location but after work.	MIN
	24-04-2024 12:22:20	Atique Salmani	Client Side	Camera can installed same location but after work.	WIN
	24-04-2024 12:22:20	Atique Salmani	Client Side	Camera can installed same location but after work.	WIN
	24-04-2024 12:22:20	Atique Salmani	Client Side	Camera can installed same location but after work.	1/1/1/
	24-04-2024 12:22:12	Atique Salmani	Client Side	Camera can installed same location but after work.	WIN
	24-04-2024 11:19:24	Atique Salmani	New		-
	23-04-2024 03:47:03	Atique Salmani	New		-
Previous Complain History	Date Time	Technician Name	Remark		
	09-12-2024 10:42:04	Atique Salmani	There is dmd activate so incoming was off now deactivate DND working ok.		
	04-12-2024 10:38:13	Siddhesh Chavan	New power supply install And dvr off issue resoved and all working ok		