

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE11882																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9820007487																			
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																
Ticket Type :	Complain	Date & Time :	13-06-2024 11:34:18																	
Vendor Details :																				
Company Name/Client Name :	Shanti Apt	Customer's Mobile :	9820007487	Name :	Rajesh Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	1-2 cameras angle need to set																			
Technician Comment :	Temprory angel set but need tonpermanent bracket need to rejoint oppsit side told to mam																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	Temprory angel set but need tonpermanent bracket need to rejoint oppsit side told to mam																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>14-06-2024 10:50:36</td><td>Atique Salmani</td><td>Completed</td><td>Temprory angel set but need tonpermanent bracket need to rejoint oppsit side told to mam</td><td></td></tr><tr><td>13-06-2024 06:37:02</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	14-06-2024 10:50:36	Atique Salmani	Completed	Temprory angel set but need tonpermanent bracket need to rejoint oppsit side told to mam		13-06-2024 06:37:02	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																
14-06-2024 10:50:36	Atique Salmani	Completed	Temprory angel set but need tonpermanent bracket need to rejoint oppsit side told to mam																	
13-06-2024 06:37:02	Atique Salmani	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>18-06-2024 10:45:28</td><td>Neeraj Chauhan</td><td>Recording showing done and footage download on pen drive and F wing tv automatically off issue solved</td></tr><tr><td>15-06-2024 05:33:26</td><td>Neeraj Chauhan</td><td>New HDMI extender installed working ok on lobby tv all cameras of floor can be seen New 8tb hard disk also installed in new nvr hard disk showing normal working okk.</td></tr></tbody></table>					Date Time	Technician Name	Remark	18-06-2024 10:45:28	Neeraj Chauhan	Recording showing done and footage download on pen drive and F wing tv automatically off issue solved	15-06-2024 05:33:26	Neeraj Chauhan	New HDMI extender installed working ok on lobby tv all cameras of floor can be seen New 8tb hard disk also installed in new nvr hard disk showing normal working okk.						
Date Time	Technician Name	Remark																		
18-06-2024 10:45:28	Neeraj Chauhan	Recording showing done and footage download on pen drive and F wing tv automatically off issue solved																		
15-06-2024 05:33:26	Neeraj Chauhan	New HDMI extender installed working ok on lobby tv all cameras of floor can be seen New 8tb hard disk also installed in new nvr hard disk showing normal working okk.																		