Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE13095 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9820007487 **No. : Technician Name** Atique Salmani **Technician Mobile :** 8080922984 Complain 23-10-2024 01:14:31 **Ticket Type : Date & Time :** Vendor Details : Shanti Apt Customer's Mobile 9820007487 Rajesh Sir Company Name : Name/Client Name Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** CCTV **Complain**: Some recording need to show F wing new exit switch and also intercom boath cable extain and working ok shifting done Technician boath recording showing painding bez client didn't received call so recording painding . **Comment** : Complain Desktop - Apurva Vajaria **Operator** : **Remark** : F wing new exit switch and also intercom boath cable extain and working ok shifting done boath recording showing painding bez client didn't received call so recording painding. **Status History : Date Time Technician Name** Status Remark Sign 24-10-2024 Atique Salmani Completed F wing new exit switch and also 12:04:21 intercom boath cable extain and working ok shifting done boath recording showing painding bez client didn't received call so recording painding . 24-10-2024 Atique Salmani New 11:03:32 Previous **Technician Name Date Time** Remark **Complain History** 13-11-2024 03:16:20 : F wing ppm done, change the CMOS battery.one camera lift 07-11-2024 10:54:44 ManojPolekar not working and chek the office.lock problem solve. Intercom ppm done. Office dvr ppm done.