## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

Service Status De	tails: VE15603						
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	9869439970						
Technician Name :	Atique Salmani		Technicia	Technician Mobile :		8080922984	
Ticket Type :	Complain	Date & Time :	21-08-202	21-08-2025 10:11:49			
Vendor Details :	•		•				
Company Name/Client Name :	Eden Garden	Customer's Mobil :	e 98694399	9869439970		Rajesh Sir	
Address:		•	•				
Mumbai , , , , Mal	harashtra						
AMC Details :							
Expiry Date :	01-01-1970 05:30:00 Type:						
<b>Product Name:</b>	CCTV						
Complain:	A wing tv again off issue camera 10 old system not working						
Technician Comment :	A wing hdmi extender 120 metr collect and old system 8 channel SMPS faulty water insert in SMPS and mouse pls infom to Rajesh sir						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	A wing hdmi extender 120 metr collect and old system 8 channel SMPS faulty water insert in SMPS and mouse pls infom to Rajesh sir						
Status History :	Date Time	Technician Name	Status	I	Remark	Sign	
	21-08-2025 10:44:56	Atique Salmani	Awaiting Spares	collect and c	PS faulty water PS and mouse pls	ALLE	
	21-08-2025 10:44:56	Atique Salmani	Awaiting Spares	collect and c	PS faulty water PS and mouse pls	Alter	
	21-08-2025 10:11:58	Atique Salmani	New			-	

Previous Complain History :	Date Time	te Time Technician Remark	
	06-09-2025 11:55:22	Atique Salmani	A wing extender installation done working ok boath wing
	05-09-2025 01:45:07	Ravi Rajbhar	Eden garden A wing lobby extension no.100 ok working 1st lift Extension no. 101 ok working 2nd lift Extension no. 102 ok working B wing B wing lobby extension no. 200 line ok working but instument kepaid issue 1st lift Extension no. 201 ok working 2nd lift Extension no. 202 OK working And society office line ok working but instument issue bcz instument in side water ????