




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE16417</b>																				
<b>Priority :</b>	Low																			
<b>Created By :</b>	Admin - Apurva Vajaria																			
<b>Complaint Mob. No. :</b>	9869439970																			
<b>Technician Name :</b>	Neeraj Chauhan		<b>Technician Mobile :</b>	8898885764																
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	08-12-2025 11:13:13																	
<b>Vendor Details :</b>																				
Company Name/Client Name :	Eden Garden	Customer's Mobile :	9869439970	Name :	Rajesh Sir															
<b>Address :</b>																				
Mumbai , , , , Maharashtra																				
<b>AMC Details :</b>																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
<b>Product Name :</b>	CCTV																			
<b>Complain :</b>	1)Basement dome camera off issue 2)A wing entrance 1 camera off issue 3)2 cameras IP 66 Box need to change																			
<b>Technician Comment :</b>	A wing entrance camera 4/4 ip 66 box install and b wing entrance camera disturbance issue solved B wing parking camera																			
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																			
<b>Remark :</b>	A wing entrance camera 4/4 ip 66 box install and b wing entrance camera disturbance issue solved B wing parking camera																			
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>08-12-2025 01:35:37</td><td>Neeraj Chauhan</td><td>Completed</td><td>A wing entrance camera 4/4 ip 66 box install and b wing entrance camera disturbance issue solved B wing parking camera</td><td></td></tr><tr><td>08-12-2025 11:14:50</td><td>Neeraj Chauhan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	08-12-2025 01:35:37	Neeraj Chauhan	Completed	A wing entrance camera 4/4 ip 66 box install and b wing entrance camera disturbance issue solved B wing parking camera		08-12-2025 11:14:50	Neeraj Chauhan	New		-
Date Time	Technician Name	Status	Remark	Sign																
08-12-2025 01:35:37	Neeraj Chauhan	Completed	A wing entrance camera 4/4 ip 66 box install and b wing entrance camera disturbance issue solved B wing parking camera																	
08-12-2025 11:14:50	Neeraj Chauhan	New		-																
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>12-12-2025 11:03:30</td><td>PratikLogade</td><td>Old canera shop saide installation don and viewing prob clear ... New hdmi extendar 30mtr intallation don all work clos</td></tr><tr><td>09-12-2025 10:41:07</td><td>Atique Salmani</td><td>A wing 101 1st lift extention nmbr A wing second. 102 lift extension nmbr B wing lift 201 extender nmbr Bwing lift 202 ext nmbr Society office moniter resolution one by one but same issue need to 10 mter hdmi cable and in open chek and observation and securty intercom issue resolved chek by mistake ji and pathak ji</td></tr></tbody></table>					Date Time	Technician Name	Remark	12-12-2025 11:03:30	PratikLogade	Old canera shop saide installation don and viewing prob clear ... New hdmi extendar 30mtr intallation don all work clos	09-12-2025 10:41:07	Atique Salmani	A wing 101 1st lift extention nmbr A wing second. 102 lift extension nmbr B wing lift 201 extender nmbr Bwing lift 202 ext nmbr Society office moniter resolution one by one but same issue need to 10 mter hdmi cable and in open chek and observation and securty intercom issue resolved chek by mistake ji and pathak ji						
Date Time	Technician Name	Remark																		
12-12-2025 11:03:30	PratikLogade	Old canera shop saide installation don and viewing prob clear ... New hdmi extendar 30mtr intallation don all work clos																		
09-12-2025 10:41:07	Atique Salmani	A wing 101 1st lift extention nmbr A wing second. 102 lift extension nmbr B wing lift 201 extender nmbr Bwing lift 202 ext nmbr Society office moniter resolution one by one but same issue need to 10 mter hdmi cable and in open chek and observation and securty intercom issue resolved chek by mistake ji and pathak ji																		