




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE4791																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9820007487																								
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																					
Ticket Type :	Complain	Date & Time :	15-02-2022 04:18:28																						
Vendor Details :																									
Company Name/Client Name :	Shanti Apt	Customer's Mobile :	9820007487	Name :	Rajesh Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	CCTV																								
Complain :	cctv f wing dvr issue																								
Technician Comment :	One SMPS faulty so one SMPS which is use only for 2 cameras so swap the fractuating cameras on this SMPS now working ok.																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	One SMPS faulty so one SMPS which is use only for 2 cameras so swap the fractuating cameras on this SMPS now working ok.																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>15-02-2022 05:27:01</td><td>Atique Salmani</td><td>Completed</td><td>One SMPS faulty so one SMPS which is use only for 2 cameras so swap the fractuating cameras on this SMPS now working ok.</td><td></td></tr><tr><td>15-02-2022 04:19:01</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>15-02-2022 04:18:29</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	15-02-2022 05:27:01	Atique Salmani	Completed	One SMPS faulty so one SMPS which is use only for 2 cameras so swap the fractuating cameras on this SMPS now working ok.		15-02-2022 04:19:01	Atique Salmani	New		-	15-02-2022 04:18:29	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
15-02-2022 05:27:01	Atique Salmani	Completed	One SMPS faulty so one SMPS which is use only for 2 cameras so swap the fractuating cameras on this SMPS now working ok.																						
15-02-2022 04:19:01	Atique Salmani	New		-																					
15-02-2022 04:18:29	Atique Salmani	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>01-02-2022 10:51:35</td><td>Ravi Rajbhar</td><td>f wing society office DVR repair return with install and all camera ok working recording going on today but recording Under observation</td></tr><tr><td>27-01-2022 11:40:43</td><td>YogeshDesai</td><td>cameras can be viewed on tv A wing lift and passage camera issue need to call liftman and electrician.</td></tr></tbody></table>					Date Time	Technician Name	Remark	01-02-2022 10:51:35	Ravi Rajbhar	f wing society office DVR repair return with install and all camera ok working recording going on today but recording Under observation	27-01-2022 11:40:43	YogeshDesai	cameras can be viewed on tv A wing lift and passage camera issue need to call liftman and electrician.											
Date Time	Technician Name	Remark																							
01-02-2022 10:51:35	Ravi Rajbhar	f wing society office DVR repair return with install and all camera ok working recording going on today but recording Under observation																							
27-01-2022 11:40:43	YogeshDesai	cameras can be viewed on tv A wing lift and passage camera issue need to call liftman and electrician.																							