Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

| Service Status Details : VE5977 | | | | | | | | |
|----------------------------------|--|---------------------|---------------------|------------|------------|--|--|--|
| Priority: | Low | | | | | | | |
| Created By: | Admin - Apurva Vajaria | | | | | | | |
| Complaint Mob. | 9869439970 | | | | | | | |
| Technician Name : | Ravi Rajbhar | | Technician Mobile : | 8080922965 | | | | |
| Ticket Type : | Complain | Date & Time : | 18-07-2022 01:02:15 | | | | | |
| Vendor Details : | | | | | | | | |
| Company Name/Client Name : | Eden Garden | Customer's Mobile : | 9869439970 | Name : | Rajesh Sir | | | |
| Address: | | | | | | | | |
| Mumbai , , , , Maharashtra | | | | | | | | |
| AMC Details : | | | | | | | | |
| Expiry Date : | 01-01-1970 05:30:00 | | Type: | | | | | |
| Product Name: | Intercom | | | | | | | |
| Complain: | please check and repair all lift intercom | | | | | | | |
| Technician Comment : | a wing 1st lift intercom issue resolved and ok working done all lift check ok working done | | | | | | | |
| Complain Operator : | Desktop - Apurva Vajaria | | | | | | | |
| Remark: | a wing 1st lift intercom issue resolved and ok working done all lift check ok working done | | | | | | | |

| Status History : | Date Time | Technician Name | Status | Remark | Sign |
|-----------------------------------|------------------------|--------------------|---|---|------|
| | 25-07-2022 11:58:19 | Ravi Rajbhar | Completed | a wing 1st lift intercom issue resolved and ok working done all lift check ok working done | Znyh |
| | 25-07-2022 11:41:17 | Ravi Rajbhar | New | | - |
| | 25-07-2022 11:41:12 | Ravi Rajbhar | New | | - |
| | 18-07-2022 03:16:33 | Ravi Rajbhar | Work Pending | Eden garden A. wing lobby 100 working ok 1st lift 101 phone issue line working ok Second lift cable break continuity from crone second floor duct to lift end we checked B wing lobby 200 ok 1st lift 201 working ok . 2nd lift issue resolved from crone working ok. | MATA |
| | 18-07-2022 01:03:08 | Ravi Rajbhar | New | | - |
| | 18-07-2022 01:02:16 | Ravi Rajbhar | New | | - |
| Previous Complain History : | Date Time | Technician Name | Remark | | |
| | 04-08-2022 10:39:06 | Atique Salmani | ppm done all working ok only 19 nmbr being lift camera black n white when show flash light it's color soncamera sensor weak need to change. | | |
| | 04-08-2022 10:37:46 | Atique Salmani | camera nmbr 16: working ok | | |