Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE8604 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9869439970 **No. :** Technician Yogesh Desai **Technician Mobile :** 8080922963 Name : Complain 17-06-2023 11:37:19 **Ticket Type : Date & Time :** Vendor Details : Eden Garden Customer's Mobile : 9869439970 Rajesh Sir Company Name : Name/Client Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** CCTV Camera no. 11 off issue **Complain**: A wing bullet camera on way to terrace on 12 th floor is faulty camera not working. Also camera **Technician** bracket broken. Faulty camera handed over to security guard phatak. Work completed **Comment** : Complain Desktop - Apurva Vajaria **Operator** : **Remark** : A wing bullet camera on way to terrace on 12 th floor is faulty camera not working. Also camera bracket broken. Faulty camera handed over to security guard phatak. Work completed **Status History :** Date Time **Technician Name** Status Remark Sign 17-06-2023 YogeshDesai Completed A wing bullet camera on way to 01:02:44 terrace on 12 th floor is faulty camera not working. Also camera bracket broken. Faulty camera handed over to security guard phatak. Work completed 17-06-2023 YogeshDesai New 11:37:28 Previous **Technician Name Date Time** Remark Complain 18-05-2023 SantoshPathak dilshad visited site 22.05.2023 11 no camera bracket **History** : 11:41:48 break 2 no camera angle setting solved 11 no camera pending 17-05-2023 Kalpesh SubhashGurav A Wing Lobby Ext.100 OK A Wing 1 Lift Ext. 101 OK A 10:36:53 Wing 2 Lift Ext. 102 OK B Wing Lobby Ext. 200 OK B Wing 1 Lift Ext. 201 OK B Wing 2 Lift Ext. 202 OK Basement Ext. Disconnect