




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE3777																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9820842494																								
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																					
Ticket Type :	Complain	Date & Time :	04-09-2021 10:14:18																						
Vendor Details :																									
Company Name/Client Name :	Bombay Deying And Manufacturing Co. Ltd	Customer's Mobile :	9820842494	Name :	Rajiv Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	31-07-2020 12:00:00		Type :	Comprehensive																					
Product Name :	CCTV																								
Complain :	DVR no. 2 camera no. 1 is not working																								
Technician Comment :	DVR no 2 - camera no 1 main gate camera ok working done only power supply faulty bcz main power supply trip confirm to mayur sir																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	DVR no 2 - camera no 1 main gate camera ok working done only power supply faulty bcz main power supply trip confirm to mayur sir																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>04-09-2021 02:05:44</td><td>Ravi Rajbhar</td><td>Completed</td><td>DVR no 2 - camera no 1 main gate camera ok working done only power supply faulty bcz main power supply trip confirm to mayur sir</td><td></td></tr><tr><td>04-09-2021 10:14:41</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>04-09-2021 10:14:18</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	04-09-2021 02:05:44	Ravi Rajbhar	Completed	DVR no 2 - camera no 1 main gate camera ok working done only power supply faulty bcz main power supply trip confirm to mayur sir		04-09-2021 10:14:41	Ravi Rajbhar	New		-	04-09-2021 10:14:18	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
04-09-2021 02:05:44	Ravi Rajbhar	Completed	DVR no 2 - camera no 1 main gate camera ok working done only power supply faulty bcz main power supply trip confirm to mayur sir																						
04-09-2021 10:14:41	Ravi Rajbhar	New		-																					
04-09-2021 10:14:18	Ravi Rajbhar	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>04-09-2021 10:15:11</td><td>Ravi Rajbhar</td><td>ppm done off CCTV system all ok working done DVR 2-. 4 camera pinkes issue also and inform to mayur sir DVR 1- 4 camera blure issue bcz cable joint and back exit gate camera issue</td></tr><tr><td>11-06-2021 12:07:15</td><td>Ravi Rajbhar</td><td>two camera replacement back side gate and old camera hondover to Rajesh sir all camera ok working done</td></tr></tbody></table>					Date Time	Technician Name	Remark	04-09-2021 10:15:11	Ravi Rajbhar	ppm done off CCTV system all ok working done DVR 2-. 4 camera pinkes issue also and inform to mayur sir DVR 1- 4 camera blure issue bcz cable joint and back exit gate camera issue	11-06-2021 12:07:15	Ravi Rajbhar	two camera replacement back side gate and old camera hondover to Rajesh sir all camera ok working done											
Date Time	Technician Name	Remark																							
04-09-2021 10:15:11	Ravi Rajbhar	ppm done off CCTV system all ok working done DVR 2-. 4 camera pinkes issue also and inform to mayur sir DVR 1- 4 camera blure issue bcz cable joint and back exit gate camera issue																							
11-06-2021 12:07:15	Ravi Rajbhar	two camera replacement back side gate and old camera hondover to Rajesh sir all camera ok working done																							