




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE11527																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9892982500																			
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																
Ticket Type :	Complain	Date & Time :	30-04-2024 10:42:48																	
Vendor Details :																				
Company Name/Client Name :	Lifescapes Mirage	Customer's Mobile :	9892982500	Name :	Rakesh Sanghavi															
Address :																				
Mumbai , , , 400028 , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	Intercom																			
Complain :	In society office new phone need to install and flat no. 1101 intercom need to check and society office phone need to install in lift																			
Technician Comment :	society office new phone install with new programming new port no.0140 and society office phone remove and install in lift and flat 1101 intercom issue resolved but instrument issue check our side																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	society office new phone install with new programming new port no.0140 and society office phone remove and install in lift and flat 1101 intercom issue resolved but instrument issue check our side																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>30-04-2024 12:44:25</td><td>Ravi Rajbhar</td><td>Completed</td><td>society office new phone install with new programming new port no.0140 and society office phone remove and install in lift and flat 1101 intercom issue resolved but instrument issue check our side</td><td></td></tr><tr><td>30-04-2024 10:42:54</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	30-04-2024 12:44:25	Ravi Rajbhar	Completed	society office new phone install with new programming new port no.0140 and society office phone remove and install in lift and flat 1101 intercom issue resolved but instrument issue check our side		30-04-2024 10:42:54	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																
30-04-2024 12:44:25	Ravi Rajbhar	Completed	society office new phone install with new programming new port no.0140 and society office phone remove and install in lift and flat 1101 intercom issue resolved but instrument issue check our side																	
30-04-2024 10:42:54	Ravi Rajbhar	New		-																

Previous Complain History :			
	Date Time	Technician Name	Remark
	23-04-2024 05:07:45	Ravi Rajbhar	society office intercom on off issue resolved and ok working done and ok camera survey done
	18-04-2024 03:46:20	Ravi Rajbhar	society office intercom ok working already 702 intercom ok working already check our side 806 intercom issue resolved and ok working done checking cable flat to duct duct to junction box then repunchiing and 505 client not approve in flat client told next time