## Vallabh Enterprises

**Regd. Office** : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 Support : | **W** : www.vallabhenterprises.com **E** : vallabhsecure@yahoo.co.in

Service Status Details : VE11724 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9892982500 **No. :** Technician Atique Salmani **Technician Mobile** 8080922984 Name : Complain 24-05-2024 04:40:37 **Ticket Type :** Date & Time : Vendor Details : Lifescapes Mirage Customer's Mobile 9892982500 Rakesh Company Name : Name/Client Sanghavi Name : Address : Mumbai, , , 400028, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** Intercom **Complain** : Watchmen cabin intercom not working and 1106/1605/1606 and also some flats intercom not working and parking camera not able to see in TV **Technician** 1606 phone not available client need to pay 1605 phone issue need to changed 1106 devide flate And security phone also faulty so installed manager cabin phone and one back side lobby camera **Comment**: was hanggin so reinstalled and gate side cameras issue resolved and 5 dvr veiwing in security cabin.and also cctv room hdmi cable need to changed 3 metr. Complain Desktop - Apurva Vajaria **Operator** : **Remark** : 1606 phone not available client need to pay 1605 phone issue need to changed 1106 devide flate And security phone also faulty so installed manager cabin phone and one back side lobby camera was hanggin so reinstalled and gate side cameras issue resolved and 5 dvr veiwing in security cabin.and also cctv room hdmi cable need to changed 3 metr . **Status History :** Technician **Date Time** Status Remark Sign Name 27-05-2024 Atique Completed 1606 phone not available client need to 03:34:01 Salmani pay 1605 phone issue need to changed 1106 devide flate And security phone also faulty so installed manager cabin phone and one back side lobby camera was hanggin so reinstalled and gate side cameras issue resolved and 5 dvr veiwing in security cabin.and also cctv room hdmi cable need to changed 3 metr. 27-05-2024 New Atique 11:25:28 Salmani

Previous Complain History :	Date Time	Technician Name	Remark
	30-05-2024 04:17:19	TauseephRaza	Society office 1 phone and Flat no.1606 phone install work completed
	11-05-2024 01:46:56	Neeraj Chauhan	Ppm done 2 nos RC use 1 nos vga cable install