


Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE4537					
Priority :	Low				
Created By :	Admin - Apurva Vajaria				
Complaint Mob. No. :	9892982500				
Technician Name :	Atique Salmani		Technician Mobile :	8080922984	
Ticket Type :	Complain	Date & Time :	06-01-2022 10:53:07		
Vendor Details :					
Company Name/Client Name :	Lifescapes Mirage	Customer's Mobile :	9892982500	Name :	Rakesh Sanghavi
Address :					
Mumbai , , , 400028 , Maharashtra					
AMC Details :					
Expiry Date :	01-01-1970 05:30:00		Type :		
Product Name :	CCTV				
Complain :	parking area camera need to align & 16th floor camera off issue, 2-3 cameras picture clarity issue & 1 camera angle need to set				
Technician Comment :	Mirage 4 dvr all cameras swap according to floor wise and naming all floor also And also Perry ferry parking area camera done in sequence Awing 16 floor camera faulty 7 floor camera reconnection and ok A wing lobby refilled bnc dc working ok A wing 15 floor camera faulty painding Parking area camera faulty painding Terrace camera fractuate camera faulty painding . Dahua dvr off becoz all cameras swap in empty port in sequence .				
Complain Operator :	Desktop - Apurva Vajaria				
Remark :	Mirage 4 dvr all cameras swap according to floor wise and naming all floor also And also Perry ferry parking area camera done in sequence Awing 16 floor camera faulty 7 floor camera reconnection and ok A wing lobby refilled bnc dc working ok A wing 15 floor camera faulty painding Parking area camera faulty painding Terrace camera fractuate camera faulty painding . Dahua dvr off becoz all cameras swap in empty port in sequence .				

Status History :	Date Time	Technician Name	Status	Remark	Sign
	06-01-2022 07:17:28	Atique Salmani	Completed	Mirage 4 dvr all cameras swap according to floor wise and naming all floor also And also Perry ferry parking area camera done in sequence A wing 16 floor camera faulty 7 floor camera reconnection and ok A wing lobby refilled bnc dc working ok A wing 15 floor camera faulty painting Parking area camera faulty painting Terrace camera fracture camera faulty painting . Dahua dvr off becoz all cameras swap in empty port in sequence .	
	06-01-2022 10:53:25	Atique Salmani	New		-
	06-01-2022 10:53:08	Atique Salmani	New		-
Previous Complain History :	Date Time	Technician Name	Remark		
	15-02-2022 02:38:30	YogeshDesai			
	15-02-2022 02:37:13	YogeshDesai	New phone installed in 805 working ok.		