## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

Service Status De	tails: VE7587						
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	9892982500						
Technician Name :	Yogesh Desai		Technic:	ian Mobile 8080922963			
Ticket Type :	Complain	Date & Time :	09-02-20	)23 11:14:48			
Vendor Details :							
Company Name/Client Name :	Lifescapes Mirage	Customer's Mobile :	9892982	2500	Name :	Rakesh Sanghavi	
Address :							
Mumbai , , , 400028 , Maharashtra							
AMC Details :							
Expiry Date :	01-01-1970 05:30:00		Type:	Type:			
<b>Product Name:</b>	CCTV						
Complain:	9 cameras off issue						
Technician Comment :	Power supply has been changed new power supply has been installed all 9 camera are working. Also switcher has been changed and parking cameras can be viewed on tv . all cameras can be viewed on tv . One camera issue of fifth floor has been sloved						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	Power supply has been changed new power supply has been installed all 9 camera are working. Also switcher has been changed and parking cameras can be viewed on tv .all cameras can be viewed on tv . One camera issue of fifth floor has been sloved						
<b>Status History:</b>	Date Time	Technician Name	Status	]	Remark	Sign	
	11-02-2023 06:51:01	YogeshDesai	Completed	Power supply has been changed new power supply has been installed all 9 camera are working. Also switcher has been changed and parking cameras can be viewed on tv . all cameras can be viewed on tv . One camera issue of fifth floor has been sloved			
	11-02-2023 04:22:29	YogeshDesai	New			-	
	09-02-2023 11:15:03	YogeshDesai	New			-	

<b>Previous</b>
Complain
<b>History</b> :

Date Time	Technician Name	Remark
06-02-2023 03:06:36	Munna Gupta	
09-01-2023 03:29:20	Ravi Rajbhar	Main gate security cabin tv viewing issue resolved and ok working done And flat no. 1302 intercom issue resolved and ok working done port faulty port no. 0034 then new port used 0144 reprogramming