

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE1879																									
Priority :	High																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9920153982																								
Technician Name :	Anil Yadav	Technician Mobile :	8080922983																						
Ticket Type :	New Installation	Date & Time :	22-09-2020 12:24:52																						
Vendor Details :																									
Company Name/Client Name :	Shree Siddhivinayak Towers CHS LTD	Customer's Mobile :	9920153982	Name :	Rakesh Shah																				
Address :																									
Mumbai , Chikoowadi, Borivali West, Mumbai, Maharashtra, India , , 400092 , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	VDP																								
Complain :	A/1201 Full Kit																								
Technician Comment :	Only screen install working fine. Camera not install because cable not proper location.																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	Only screen install working fine. Camera not install because cable not proper location.																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>22-09-2020 01:26:34</td><td>AnilYadav</td><td>Completed</td><td>Only screen install working fine. Camera not install because cable not proper location.</td><td></td></tr><tr><td>22-09-2020 12:28:39</td><td>AnilYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>22-09-2020 12:24:52</td><td>AnilYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	22-09-2020 01:26:34	AnilYadav	Completed	Only screen install working fine. Camera not install because cable not proper location.		22-09-2020 12:28:39	AnilYadav	New		-	22-09-2020 12:24:52	AnilYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																					
22-09-2020 01:26:34	AnilYadav	Completed	Only screen install working fine. Camera not install because cable not proper location.																						
22-09-2020 12:28:39	AnilYadav	New		-																					
22-09-2020 12:24:52	AnilYadav	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>21-10-2020 11:21:32</td><td>Ravi Rajbhar</td><td>biometric attendance machine licences key update done and data download proper and one ueser dilit</td></tr><tr><td>21-10-2020 11:20:17</td><td>Ravi Rajbhar</td><td>a wing 904. vdp screen faulty and return office and check</td></tr></tbody></table>					Date Time	Technician Name	Remark	21-10-2020 11:21:32	Ravi Rajbhar	biometric attendance machine licences key update done and data download proper and one ueser dilit	21-10-2020 11:20:17	Ravi Rajbhar	a wing 904. vdp screen faulty and return office and check											
Date Time	Technician Name	Remark																							
21-10-2020 11:21:32	Ravi Rajbhar	biometric attendance machine licences key update done and data download proper and one ueser dilit																							
21-10-2020 11:20:17	Ravi Rajbhar	a wing 904. vdp screen faulty and return office and check																							