







# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE2128</b>																														
<b>Priority :</b>	High																													
<b>Created By :</b>	Admin - Apurva Vajaria																													
<b>Complaint Mob. No. :</b>	9820126185																													
<b>Technician Name :</b>	Yasin Shaikh		<b>Technician Mobile :</b>	8689802313																										
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	28-10-2020 12:47:06																											
<b>Vendor Details :</b>																														
<b>Company Name/Client Name :</b>	Sotex India Pvt Ltd	<b>Customer's Mobile :</b>	9820126185	<b>Name :</b>	Ramaswami Sir																									
<b>Address :</b>																														
Mumbai , , , , Maharashtra																														
<b>AMC Details :</b>																														
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>																											
<b>Product Name :</b>	CCTV																													
<b>Complain :</b>	extender issue																													
<b>Technician Comment :</b>	extender change for both tv working ok (with mayur)																													
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																													
<b>Remark :</b>	extender change for both tv working ok (with mayur)																													
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>02-11-2020 12:27:30</td><td>YasinShaikh</td><td>Completed</td><td>extender change for both tv working ok (with mayur)</td><td></td></tr><tr><td>28-10-2020 06:14:04</td><td>YasinShaikh</td><td>Work Pending</td><td>We have checked the system , there is Hdmi extender issue so it is fluctuating.</td><td></td></tr><tr><td>28-10-2020 12:47:26</td><td>YasinShaikh</td><td>New</td><td></td><td>-</td></tr><tr><td>28-10-2020 12:47:06</td><td>YasinShaikh</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	02-11-2020 12:27:30	YasinShaikh	Completed	extender change for both tv working ok (with mayur)		28-10-2020 06:14:04	YasinShaikh	Work Pending	We have checked the system , there is Hdmi extender issue so it is fluctuating.		28-10-2020 12:47:26	YasinShaikh	New		-	28-10-2020 12:47:06	YasinShaikh	New		-
Date Time	Technician Name	Status	Remark	Sign																										
02-11-2020 12:27:30	YasinShaikh	Completed	extender change for both tv working ok (with mayur)																											
28-10-2020 06:14:04	YasinShaikh	Work Pending	We have checked the system , there is Hdmi extender issue so it is fluctuating.																											
28-10-2020 12:47:26	YasinShaikh	New		-																										
28-10-2020 12:47:06	YasinShaikh	New		-																										
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>03-12-2020 10:14:40</td><td>Atique Salmani</td><td></td></tr><tr><td>18-11-2020 10:50:56</td><td>MayurYadav</td><td>HDMI extender change (Rx)</td></tr></tbody></table>					Date Time	Technician Name	Remark	03-12-2020 10:14:40	Atique Salmani		18-11-2020 10:50:56	MayurYadav	HDMI extender change (Rx)																
Date Time	Technician Name	Remark																												
03-12-2020 10:14:40	Atique Salmani																													
18-11-2020 10:50:56	MayurYadav	HDMI extender change (Rx)																												