

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE14902																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9821431296																			
Technician Name :	Pravin Jagade		Technician Mobile :	7262044153																
Ticket Type :	Complain	Date & Time :	03-06-2025 01:58:19																	
Vendor Details :																				
Company Name/Client Name :	SHETH BUILDERS PVT. LTD(SHETH SUPREME)	Customer's Mobile :	9821431296	Name :	Ratnesh Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	lobby phone outgoing not working																			
Technician Comment :																				
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :																				
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>03-06-2025 03:58:30</td><td>PravinJagade</td><td>New</td><td></td><td>-</td></tr><tr><td>03-06-2025 01:58:26</td><td>PravinJagade</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	03-06-2025 03:58:30	PravinJagade	New		-	03-06-2025 01:58:26	PravinJagade	New		-
Date Time	Technician Name	Status	Remark	Sign																
03-06-2025 03:58:30	PravinJagade	New		-																
03-06-2025 01:58:26	PravinJagade	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>26-04-2025 10:29:33</td><td>Siddhesh Chavan</td><td>Back side door new bolt lock install and working ok</td></tr><tr><td>02-04-2025 10:40:31</td><td>Ravi Rajbhar</td><td>1301 line ok instrument issue 1305 not used phone 1201 line ok instrument issue 1103 issue resolved 1105 cable missing sift cable 1003 next time asking client 901 cable missing 902 cable remove duct side 905 door lock 701 cable remove duct side 602 line ok instrument remove client side 501 door lock 506 line 402 line ok 404 door lock 405 line ok instrument issue keypaid 301 next time asking client 201 cable missing and telephone remove also juct 202 not uesd phone 101 phone missing 103 issue resolved</td></tr></tbody></table>					Date Time	Technician Name	Remark	26-04-2025 10:29:33	Siddhesh Chavan	Back side door new bolt lock install and working ok	02-04-2025 10:40:31	Ravi Rajbhar	1301 line ok instrument issue 1305 not used phone 1201 line ok instrument issue 1103 issue resolved 1105 cable missing sift cable 1003 next time asking client 901 cable missing 902 cable remove duct side 905 door lock 701 cable remove duct side 602 line ok instrument remove client side 501 door lock 506 line 402 line ok 404 door lock 405 line ok instrument issue keypaid 301 next time asking client 201 cable missing and telephone remove also juct 202 not uesd phone 101 phone missing 103 issue resolved						
Date Time	Technician Name	Remark																		
26-04-2025 10:29:33	Siddhesh Chavan	Back side door new bolt lock install and working ok																		
02-04-2025 10:40:31	Ravi Rajbhar	1301 line ok instrument issue 1305 not used phone 1201 line ok instrument issue 1103 issue resolved 1105 cable missing sift cable 1003 next time asking client 901 cable missing 902 cable remove duct side 905 door lock 701 cable remove duct side 602 line ok instrument remove client side 501 door lock 506 line 402 line ok 404 door lock 405 line ok instrument issue keypaid 301 next time asking client 201 cable missing and telephone remove also juct 202 not uesd phone 101 phone missing 103 issue resolved																		