

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE11352																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	7021671156																			
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																
Ticket Type :	Complain	Date & Time :	10-04-2024 01:15:43																	
Vendor Details :																				
Company Name/Client Name :	Lokhandwala Foundation	Customer's Mobile :	7021671156	Name :	Rauf Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	2 replacement HDD need to install																			
Technician Comment :																				
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	Replacement HDD handover done to shinde sir as discussed with Rauf sir																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>12-04-2024 12:38:52</td><td>Ravi Rajbhar</td><td>Completed</td><td></td><td>-</td></tr><tr><td>12-04-2024 11:30:26</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	12-04-2024 12:38:52	Ravi Rajbhar	Completed		-	12-04-2024 11:30:26	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																
12-04-2024 12:38:52	Ravi Rajbhar	Completed		-																
12-04-2024 11:30:26	Ravi Rajbhar	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>28-03-2024 12:02:22</td><td>Atique Salmani</td><td>Today30/30/24 409 207 BNC connector changed from dvr end and reconnection from camera end 205/206/201/109/111/208/107/108/ totally cameras need to changed and also 204 112 ohms not getting Dvr nmbr 4 hdd not detect so changed hdd hdd given by rauf sir and formatted hddd now working ok on under observation. 204 power ok ohms cable issue 110 reconnection camera end ok 208 reconnection camera end ok 5 nmbr dvr new hdd installed hdd given by rauf sir 402 speaker okk connection removed.412 speak okk connection remove,412 passage speak ok connection remove 410 peaker faultiy. 404 speaker okk connection remove, 310 alredy working,307 alredy working, 303 already working,202 already working</td></tr><tr><td>12-03-2024 03:21:00</td><td>MayurYadav</td><td>Survey done for camera Require 4 new camera in lab Check old system</td></tr></tbody></table>					Date Time	Technician Name	Remark	28-03-2024 12:02:22	Atique Salmani	Today30/30/24 409 207 BNC connector changed from dvr end and reconnection from camera end 205/206/201/109/111/208/107/108/ totally cameras need to changed and also 204 112 ohms not getting Dvr nmbr 4 hdd not detect so changed hdd hdd given by rauf sir and formatted hddd now working ok on under observation. 204 power ok ohms cable issue 110 reconnection camera end ok 208 reconnection camera end ok 5 nmbr dvr new hdd installed hdd given by rauf sir 402 speaker okk connection removed.412 speak okk connection remove,412 passage speak ok connection remove 410 peaker faultiy. 404 speaker okk connection remove, 310 alredy working,307 alredy working, 303 already working,202 already working	12-03-2024 03:21:00	MayurYadav	Survey done for camera Require 4 new camera in lab Check old system						
Date Time	Technician Name	Remark																		
28-03-2024 12:02:22	Atique Salmani	Today30/30/24 409 207 BNC connector changed from dvr end and reconnection from camera end 205/206/201/109/111/208/107/108/ totally cameras need to changed and also 204 112 ohms not getting Dvr nmbr 4 hdd not detect so changed hdd hdd given by rauf sir and formatted hddd now working ok on under observation. 204 power ok ohms cable issue 110 reconnection camera end ok 208 reconnection camera end ok 5 nmbr dvr new hdd installed hdd given by rauf sir 402 speaker okk connection removed.412 speak okk connection remove,412 passage speak ok connection remove 410 peaker faultiy. 404 speaker okk connection remove, 310 alredy working,307 alredy working, 303 already working,202 already working																		
12-03-2024 03:21:00	MayurYadav	Survey done for camera Require 4 new camera in lab Check old system																		