## Vallabh Enterprises

**Regd. Office** : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE7506 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 7021671156 **No. : Technician Name Technician Mobile** 8080922965 Ravi Rajbhar 01-02-2023 10:44:10 **Ticket Type :** Complain **Date & Time : Vendor Details :** Lokhandwala Customer's Mobile 7021671156 Rauf Sir Company Name : Name/Client Name Foundation Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** EPABX **Complain** : EPABX line off issue Panasonic epbax system check ex. No ok working done but co line issue bcz Panasonic systems Technician **Comment** : basic card issue inform to Rauf sir two CO line working CO1/CO3 /MTNL or Aeritel Complain Desktop - Apurva Vajaria **Operator** : **Remark** : Panasonic epbax system check ex. No ok working done but co line issue bcz Panasonic systems basic card issue inform to Rauf sir two CO line working CO1/CO3 /MTNL or Aeritel **Status History :** Technician **Date Time** Status Sign Remark Name 01-02-2023 Ravi Rajbhar Work Panasonic epbax system check 02:34:12Pending ex. No ok working done but co line issue bcz Panasonic systems basic card issue inform to Rauf sir two CO line working CO1/CO3 /MTNL or Aeritel 01-02-2023 New Ravi Rajbhar 10:44:36 **Previous Technician Name** Remark **Date Time Complain History** 19-07-2023 Munna Gupta I have checked 7 DVR and have set frame rate and bit rate in 11:56:10 all DVR's DVR No. 3 HDD is not getting supported and 3 cameras are connected in it and due to HDD unsupported there will be no recording for the said 3 cameras Note : If DVR restarts Data and Time gets change and due to which no recording will not be found. We recommend to replace the DVR's 30-06-2023 Ravi Rajbhar 10:55:26