




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support :** | **W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE2161</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9833922972																								
<b>Technician Name :</b>	Yogesh Desai		<b>Technician Mobile :</b>	8080922963																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	03-11-2020 09:54:44																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	Bombay Deyng And Manufacturing Co. Ltd	Customer's Mobile :	9833922972	Name :	Reddy Sir																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
Expiry Date :	31-07-2020 12:00:00		Type :	Comprehensive																					
<b>Product Name :</b>	CCTV																								
<b>Complain :</b>	camera #15 & 16 in DVR # 01, installed at ground floor VIP lift & HRC gate are not working.																								
<b>Technician Comment :</b>	two cameras power supply changed issue was of supply main gate camera power supply switch was off all three cameras are working and can be viewed on monitor compliant sloved																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	two cameras power supply changed issue was of supply main gate camera power supply switch was off all three cameras are working and can be viewed on monitor compliant sloved																								
<b>Status History :</b>	<table border="1"> <thead> <tr> <th>Date Time</th> <th>Technician Name</th> <th>Status</th> <th>Remark</th> <th>Sign</th> </tr> </thead> <tbody> <tr> <td>03-11-2020 12:48:26</td> <td>YogeshDesai</td> <td>Completed</td> <td>two cameras power supply changed issue was of supply main gate camera power supply switch was off all three cameras are working and can be viewed on monitor compliant sloved</td> <td></td> </tr> <tr> <td>03-11-2020 09:55:13</td> <td>YogeshDesai</td> <td>New</td> <td></td> <td>-</td> </tr> <tr> <td>03-11-2020 09:54:44</td> <td>YogeshDesai</td> <td>New</td> <td></td> <td>-</td> </tr> </tbody> </table>					Date Time	Technician Name	Status	Remark	Sign	03-11-2020 12:48:26	YogeshDesai	Completed	two cameras power supply changed issue was of supply main gate camera power supply switch was off all three cameras are working and can be viewed on monitor compliant sloved		03-11-2020 09:55:13	YogeshDesai	New		-	03-11-2020 09:54:44	YogeshDesai	New		-
Date Time	Technician Name	Status	Remark	Sign																					
03-11-2020 12:48:26	YogeshDesai	Completed	two cameras power supply changed issue was of supply main gate camera power supply switch was off all three cameras are working and can be viewed on monitor compliant sloved																						
03-11-2020 09:55:13	YogeshDesai	New		-																					
03-11-2020 09:54:44	YogeshDesai	New		-																					
<b>Previous Complain History :</b>	<table border="1"> <thead> <tr> <th>Date Time</th> <th>Technician Name</th> <th>Remark</th> </tr> </thead> <tbody> <tr> <td>18-11-2020 11:49:32</td> <td>YogeshDesai</td> <td>one camera issue sloved power supply switch was off . now camera can be viewed on monitor.work completed</td> </tr> <tr> <td>12-10-2020 12:18:32</td> <td>YogeshDesai</td> <td>new bracket of main gate bullet camera had been done camera work done work completed</td> </tr> </tbody> </table>					Date Time	Technician Name	Remark	18-11-2020 11:49:32	YogeshDesai	one camera issue sloved power supply switch was off . now camera can be viewed on monitor.work completed	12-10-2020 12:18:32	YogeshDesai	new bracket of main gate bullet camera had been done camera work done work completed											
Date Time	Technician Name	Remark																							
18-11-2020 11:49:32	YogeshDesai	one camera issue sloved power supply switch was off . now camera can be viewed on monitor.work completed																							
12-10-2020 12:18:32	YogeshDesai	new bracket of main gate bullet camera had been done camera work done work completed																							