

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE4510																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9029000445																								
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																					
Ticket Type :	Complain	Date & Time :	02-01-2022 11:53:53																						
Vendor Details :																									
Company Name/Client Name :	Poonam Cluster	Customer's Mobile :	9029000445	Name :	Ritu Gupta																				
Address :																									
Mumbai , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	Access																								
Complain :	Boom barrier issue																								
Technician Comment :	the pole was misbalance so remooved and refixe by cement screw and all working ok .																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	the pole was misbalance so remooved and refixe by cement screw and all working ok .																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>02-01-2022 12:40:58</td><td>Atique Salmani</td><td>Completed</td><td>the pole was misbalance so remooved and refixe by cement screw and all working ok .</td><td></td></tr><tr><td>02-01-2022 11:54:45</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>02-01-2022 11:53:53</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	02-01-2022 12:40:58	Atique Salmani	Completed	the pole was misbalance so remooved and refixe by cement screw and all working ok .		02-01-2022 11:54:45	Atique Salmani	New		-	02-01-2022 11:53:53	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
02-01-2022 12:40:58	Atique Salmani	Completed	the pole was misbalance so remooved and refixe by cement screw and all working ok .																						
02-01-2022 11:54:45	Atique Salmani	New		-																					
02-01-2022 11:53:53	Atique Salmani	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>31-01-2022 10:23:36</td><td>Ravi Rajbhar</td><td></td></tr><tr><td>13-01-2022 10:04:10</td><td>MayurYadav</td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	31-01-2022 10:23:36	Ravi Rajbhar		13-01-2022 10:04:10	MayurYadav												
Date Time	Technician Name	Remark																							
31-01-2022 10:23:36	Ravi Rajbhar																								
13-01-2022 10:04:10	MayurYadav																								