Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 Support : | **W** : www.vallabhenterprises.com **E** : vallabhsecure@yahoo.co.in

Service Status Details : VE10211 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9820242335 **No. : Technician** Ravi Rajbhar **Technician Mobile :** 8080922965 Name : Complain 07-12-2023 12:57:50 **Ticket Type : Date & Time : Vendor Details :** Customer's Mobile 9820242335 Riyaz Sir Company Shatrunjay Name : Name/Client Darshan Society Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** CCTV **Complain**: A wing lift camera off issue and office dVR time issue a wing automatically lift camera no video issue resolved and ok working done tp link trash meter **Technician** reshiver adapter lan port issue then old second lift used adapter and ok working done and faulty **Comment** : adapter lan port issue remove and take to office Complain Desktop - Apurva Vajaria **Operator** : a wing automatically lift camera no video issue resolved and ok working done tp link trash meter **Remark** : reshiver adapter lan port issue then old second lift used adapter and ok working done and faulty adapter lan port issue remove and take to office **Status History :** Technician **Date Time** Status Sign Remark Name 12-12-2023 Ravi Rajbhar Completed a wing automatically lift camera no 02:34:15 video issue resolved and ok working done tp link trash meter reshiver adapter lan port issue then old second lift used adapter and ok working done and faulty adapter lan port issue remove and take to office 12-12-2023 Ravi Rajbhar New 10:17:06 09-12-2023 Ravi Rajbhar New 06:26:23 **Previous Date Time** Technician Name Remark Complain 27-12-2023 12:54:48 Sonu Kumar C wing lift camera off issue resolved working ok **History** : 23-12-2023 01:28:53 Sonu Kumar A wing adupter handover to riraj sir