## Vallabh Enterprises

**Regd. Office** : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE10433 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9820242335 **No. :** Technician Sonu Kumar **Technician Mobile :** 8454016444 Name : Complain 02-01-2024 04:38:45 **Ticket Type :** Date & Time : **Vendor Details :** Customer's Mobile 9820242335 Riyaz Sir Company Shatrunjay Name : Name/Client Darshan Society Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** CCTV **Complain**: C wing lift camera again off issue C wing lift transmetar and reciver reconfiguration done camera ok and security cabin camera Technician install working ok and c wing pump room side cabling in client side camera working ok **Comment** : Complain Desktop - Apurva Vajaria **Operator** : C wing lift transmetar and reciver reconfiguration done camera ok and security cabin camera **Remark** : install working ok and c wing pump room side cabling in client side camera working ok **Status History :** Technician Date Time Status Remark Sign Name 09-01-2024 Sonu Kumar Completed C wing lift transmetar and reciver 06:05:46 reconfiguration done camera ok and security cabin camera install working ok and c wing pump room side cabling in client side camera working ok 09-01-2024 Sonu Kumar New 10:09:14 **Previous Technician Name** Remark **Date Time** Complain 12-01-2024 01:36:45 Sonu Kumar Temple side camera cable 1green pair cable faulty and 3 pair History : camera working ok 27-12-2023 12:54:48 C wing lift camera off issue resolved working ok Sonu Kumar