

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE14415															
Priority :	Low														
Created By :	Admin - Apurva Vajaria														
Complaint Mob. No. :	9820242335														
Technician Name :	Pravin Jagade		Technician Mobile :	7262044153											
Ticket Type :	Complain	Date & Time :	02-04-2025 01:22:26												
Vendor Details :															
Company Name/Client Name :	Shatrunjay Darshan Society	Customer's Mobile :	9820242335	Name :	Riyaz Sir										
Address :															
Mumbai , , , , Maharashtra															
AMC Details :															
Expiry Date :	01-01-1970 05:30:00		Type :												
Product Name :	CCTV														
Complain :	A wing lift no.2, C wing lobby, C wing pump room, C wing lift 1, C wing lift 2, B wing lift 1, B wing backside, C wing frontside , security cabin, all cameras off issue														
Technician Comment :															
Complain Operator :	Desktop - Apurva Vajaria														
Remark :	A wing lift no.2, C wing lobby, C wing pump room, C wing lift 1, C wing lift 2, B wing lift 1, B wing backside, C wing frontside , security cabin, all cameras issue resolved														
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>03-04-2025 10:23:36</td><td>PravinJagade</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	03-04-2025 10:23:36	PravinJagade	New		-
Date Time	Technician Name	Status	Remark	Sign											
03-04-2025 10:23:36	PravinJagade	New		-											
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>06-05-2025 11:34:31</td><td>Neeraj Chauhan</td><td>Turf out side camera installation done security cabin camera not working temporary b wing lobby camera sift to security</td></tr><tr><td>03-02-2025 01:27:10</td><td>Siddhesh Chavan</td><td>Camera working ok</td></tr></tbody></table>					Date Time	Technician Name	Remark	06-05-2025 11:34:31	Neeraj Chauhan	Turf out side camera installation done security cabin camera not working temporary b wing lobby camera sift to security	03-02-2025 01:27:10	Siddhesh Chavan	Camera working ok	
Date Time	Technician Name	Remark													
06-05-2025 11:34:31	Neeraj Chauhan	Turf out side camera installation done security cabin camera not working temporary b wing lobby camera sift to security													
03-02-2025 01:27:10	Siddhesh Chavan	Camera working ok													