Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Deta	ails: VE16421					
Priority:	Low					
Created By:	Admin - Apurva Vajaria					
Complaint Mob. No. :	9820242335					
Technician Name	Maroof Raza		Technic:	chnician Mobile 7761863562		
Ticket Type :	Complain	Date & Time:	08-12-2	08-12-2025 01:27:53		
Vendor Details :			•			
Company Name/Client Name :	Shatrunjay Darshan Society	Customer's Mobile:	e 9820242335		Name :	Riyaz Sir
Address :			•			
Mumbai , , , , Maha	arashtra					
AMC Details :						
Expiry Date :	01-01-1970 05:30:00 Type:					
Product Name:	CCTV					
Complain:	C wing lobby new replacement dome camera need to install against faulty					
Technician Comment :	C wing loby camera install one garage camera issue resolved one camera angel set camera add changing one NVR to 2nd NVR					
Complain Operator :	Desktop - Apurva Vajaria					
Remark:	C wing loby camera install one garage camera issue resolved one camera angel set camera add changing one NVR to 2nd NVR					
Status History :	Date Time	Technician Name	Status	Remark		Sign
	08-12-2025 03:36:32	MaroofRaza	Completed	C wing loby camera install one garage camera issue resolved one camera angel set camera add changing one NVR to 2nd NVR		
	08-12-2025 01:28:09	MaroofRaza	New			-
Previous Complain History :	Date Time	Technician Name	Remark			
	29-11-2025 11:09:07	Prashant Paswan	A wing back side wire 2 green white faulty cemera on/b wing bike side/ c wing tarrece/1 cemera ip shifting/ d wing h on			
	19-11-2025 10:45:20	PratikLogade	A wing back side lobby 1 par cable faulty C wing trace cable not found 3 camera on			