






# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE8680</b>					
<b>Priority :</b>	Low				
<b>Created By :</b>	Admin - Apurva Vajaria				
<b>Complaint Mob. No. :</b>	9820242335				
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984	
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	27-06-2023 10:25:39		
<b>Vendor Details :</b>					
<b>Company Name/Client Name :</b>	Shatrunjay Darshan Society	<b>Customer's Mobile :</b>	9820242335	<b>Name :</b>	Riyaz Sir
<b>Address :</b>					
Mumbai , , , , Maharashtra					
<b>AMC Details :</b>					
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>		
<b>Product Name :</b>	CCTV				
<b>Complain :</b>	lift cameras off issue				
<b>Technician Comment :</b>	A wing jali lift painding bezc receevr adaptor faulty receiver and adaptor hand over to riyaj sir and back side garage bullet camera fixed .				
<b>Complain Operator :</b>	Desktop - Apurva Vajaria				
<b>Remark :</b>	A wing jali lift painding bezc receevr adaptor faulty receiver and adaptor hand over to riyaj sir and back side garage bullet camera fixed .				

Status History :					
	Date Time	Technician Name	Status	Remark	Sign
	24-07-2023 11:30:17	Atique Salmani	Work Pending	A wing jali lift painting becuz receevr adaptor faulty receiver and adaptor hand over to riyaj sir and back side garage bullet camera fixed .	
	24-07-2023 11:21:04	Atique Salmani	New		-
	18-07-2023 06:23:42	Atique Salmani	Work Pending	A wing auto matic lift issue resolved there is problem in cable lft roof to base .A wing automatic lift 2 access ip 192.168.1.1.201 Client ip 19.168.1.202 Camera ip 192.168.1.160 Password 123456. A wing jali lift adaptor missing and also power not getting in socket .	
	18-07-2023 10:33:54	Atique Salmani	New		-
	17-07-2023 12:03:31	Atique Salmani	Work Pending	a wing 1 lift adapter reinstall and 1 NVA all camera off issue resoved and lift camera issue pending	
	17-07-2023 10:39:42	Atique Salmani	New		-
	03-07-2023 03:26:36	Atique Salmani	Work Pending	B wing lift camera issue resolved and a wing to link device adaptor issue so collect for recheck and toilet side side camera break temprrory installation done .	
	03-07-2023 10:38:20	Atique Salmani	New		-
	01-07-2023 11:10:48	Atique Salmani	New		-
	27-06-2023 04:46:47	Atique Salmani	Work Pending	Lift a wing 1 no. Lift camera ok and and 1 camera angal setting done lift b wing 2 no. Lift camera and a wing 2 no. Camera pending wark	
	27-06-2023 10:25:46	Atique Salmani	New		-
Previous Complain History :					
	Date Time	Technician Name	Remark		
	08-08-2023 01:08:07	Shiva Meena			
	05-08-2023 01:03:54	ChandanYadav	Main gate camera working and cwing fornt side camera working ok.		