







# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE77</b>																														
<b>Priority :</b>	Low																													
<b>Created By :</b>	Admin - Apurva Vajaria																													
<b>Complaint Mob. No. :</b>	9820654174																													
<b>Technician Name :</b>	Sachin Pawar	<b>Technician Mobile :</b>	8080922981																											
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	17-08-2019 10:47:14																											
<b>Vendor Details :</b>																														
Company Name/Client Name :	Dayanand Consultancy	Customer's Mobile :	9820654174	Name :	Rohan R Saple																									
<b>Address :</b>																														
Mumbai , Andheri East, Mumbai, Maharashtra, India , , 400069 , Maharashtra																														
<b>AMC Details :</b>																														
Expiry Date :	31-08-2020 12:00:00	Type :	Non-Comprehensive																											
<b>Product Name :</b>	CCTV																													
<b>Complain :</b>	CCTV issue on Chargeable basis visiting charges 750																													
<b>Technician Comment :</b>	faulty power supply is replaced with new self power supply. remote viewing is pending for static ip.																													
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																													
<b>Remark :</b>	faulty power supply is replaced with new self power supply. remote viewing is pending for static ip.																													
<b>Status History :</b>	<table border="1"> <thead> <tr> <th>Date Time</th> <th>Technician Name</th> <th>Status</th> <th>Remark</th> <th>Sign</th> </tr> </thead> <tbody> <tr> <td>20-09-2019 12:31:32</td> <td>SachinPawar</td> <td>Completed</td> <td></td> <td>-</td> </tr> <tr> <td>28-08-2019 01:24:38</td> <td>SachinPawar</td> <td>Client Side</td> <td>faulty power supply is replaced with new self power supply. remote viewing is pending for static ip.</td> <td></td> </tr> <tr> <td>20-08-2019 07:02:29</td> <td>SachinPawar</td> <td>Client Side</td> <td>All camera working ok and power supply faulty and hdd issue and online pending client side cash by 750 chargeable basis</td> <td></td> </tr> <tr> <td>17-08-2019 10:47:15</td> <td>SachinPawar</td> <td>New</td> <td></td> <td>-</td> </tr> </tbody> </table>					Date Time	Technician Name	Status	Remark	Sign	20-09-2019 12:31:32	SachinPawar	Completed		-	28-08-2019 01:24:38	SachinPawar	Client Side	faulty power supply is replaced with new self power supply. remote viewing is pending for static ip.		20-08-2019 07:02:29	SachinPawar	Client Side	All camera working ok and power supply faulty and hdd issue and online pending client side cash by 750 chargeable basis		17-08-2019 10:47:15	SachinPawar	New		-
Date Time	Technician Name	Status	Remark	Sign																										
20-09-2019 12:31:32	SachinPawar	Completed		-																										
28-08-2019 01:24:38	SachinPawar	Client Side	faulty power supply is replaced with new self power supply. remote viewing is pending for static ip.																											
20-08-2019 07:02:29	SachinPawar	Client Side	All camera working ok and power supply faulty and hdd issue and online pending client side cash by 750 chargeable basis																											
17-08-2019 10:47:15	SachinPawar	New		-																										
<b>Previous Complain History :</b>	<table border="1"> <thead> <tr> <th>Date Time</th> <th>Technician Name</th> <th>Remark</th> </tr> </thead> <tbody> <tr> <td colspan="3"> </td> </tr> </tbody> </table>					Date Time	Technician Name	Remark																						
Date Time	Technician Name	Remark																												