## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

Service Status De	tails: VE6902					
Priority:	Low					
Created By:	Admin - Apurva Vajaria					
Complaint Mob. No. :	8999161438					
Technician Name :	Siddhesh Chavan		Technician I	<b>Mobile</b> 8080922985	8080922985	
Ticket Type :	Complain Date & Time:		21-11-2022 1	2:37:20		
Vendor Details :					_	
Company Name/Client Name :	Rahul Degree Collage Nalasopara : Customer's Mol West		8999161438	Name:	Rohan Sir	
Address:						
Mumbai , , , , Ma	harashtra					
AMC Details :						
Expiry Date :	01-01-1970 05:30:00		Type:			
<b>Product Name:</b>	CCTV					
Complain:	1) Software is not working in Principal Desktop. 2) Multiple Cameras are not working at different floors. 3) The Software date and year is not updated; it is running in the year 2000.					
Technician Comment :	ground to 2nd floor CCTV survey done and date time ok					
Complain Operator :	Desktop - Apurva Vajaria					
Remark:	ground to 2nd floor CCTV survey done and date time ok					
Status History :	Date Time	Technician Name	Status	Remark	Sign	
	29-11-2022 04:44:00	Siddhesh Chavan	Completed	ground to 2nd floor CCTV survey done and date time ok	The state of the s	
	29-11-2022 03:54:27	Siddhesh Chavan	New		-	
	23-11-2022 05:11:26	Siddhesh Chavan	Work Pending	Ground to 2nd floor CCT survey done and first floor and 2 nd floor Dvr take to office for checking Standby dvr ins		
	22-11-2022 10:40:58	Siddhesh Chavan	New		-	
	21-11-2022 12:37:26	Siddhesh Chavan	New		-	

Previous Complain History :	Date Time	Technician Name	Remark
	25-08-2022 10:24:36	Sonu Kumar	3 dome camera install working ok ground floor and first floor camera 1 camera staff room and 1 room no 104 camera install working and third floor 3camera power supply install working ok and 1 dvr power supply install working ok date time issue have set again and kept on observation
	28-02-2022 01:23:23		Attend by prashant: 3 Floor DVR online done, 3 PC IVMS software install same camera Blure need to change / Repair