Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status	Details: VE15503						
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	9082608187						
Technician Name :	Rahul Mhapralkar		Technician Mobile :	9168762949			
Ticket Type:	Complain	Date &	Time :	06-08-2025 11:46:40			
Vendor Details	Vendor Details :						
Company Name/Client Name :	MAHAVIR SQUAR	RE Custome	er's Mobile :	9082608187	Name :	Rohit Sir	
Address:	-	•					
Mumbai , , , ,	Maharashtra						
AMC Details :							
Expiry Date :	01-01-1970 05:30:00			Type:			
Product Name :	VDP						
Complain:	A 2401 VDP issue need to check B-501 VDP issue (98206055881) A-1201 VDP issue (9664420055)						
Technician Comment :	A wing 2105,2401,704,1201,1704,1705 vdp installation work done, now working normally. B 501 vdp calling issue resolved, A1402 vdp calling issue resolved, A 2201 outdoor Camera issue change this device nd issue resolved						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	A wing 2105,2401,704,1201,1704,1705 vdp installation work done, now working normally. B 501 vdp calling issue resolved, A1402 vdp calling issue resolved, A 2201 outdoor Camera issue change this device nd issue resolved						
Status History :	Date Time	Technician Name	Status	Remark		Sign	
		Rahul Mhapralkar	Completed	A wing 2105,2401,704,1201, installation work done, now normally. B 501 vdp calling i A1402 vdp calling issue resolutdoor Camera issue chang issue resolved	working ssue resolved, lved, A 2201	Just	
		Rahul Mhapralkar	Completed	A wing 2105,2401,704,1201, installation work done, now normally. B 501 vdp calling i A1402 vdp calling issue reso outdoor Camera issue chang issue resolved	working ssue resolved, lved, A 2201	Dise	
		Rahul Mhapralkar	New			-	

Previous Complain History :	Date Time	Technician Name	Remark
	29-08-2025 10:38:36	Rahul Mhapralkar	B wing 2401 vdp calling issue resolved, B wing 1201 Vdp calling issue resolved, 1901 vdp calling issue resolved, A wing 1103 vdp installed,604 Vdp installed, A wing calling issue resolved, now A & B intercom working normally
	20-08-2025 10:33:47	Rahul Mhapralkar	1904 vdp out camera calling issue resolved now working normally.