

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE8454																																			
Priority :	Low																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	9029999160																																		
Technician Name :	Chandan Yadav		Technician Mobile :	9833262842																															
Ticket Type :	Complain	Date & Time :	30-05-2023 05:17:26																																
Vendor Details :																																			
Company Name/Client Name :	Fortune Acres Malik Bhai	Customer's Mobile :	9029999160	Name :	Sahil Bhai																														
Address :																																			
Mumbai , , , , Maharashtra																																			
AMC Details :																																			
Expiry Date :	01-01-1970 05:30:00		Type :																																
Product Name :	CCTV																																		
Complain :	In Director cabin TV Cameras lagging issue																																		
Technician Comment :	In directer room tv legging ieesu solve.																																		
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :	In directer room tv legging ieesu solve.																																		
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>01-06-2023 01:40:46</td><td>ChandanYadav</td><td>Completed</td><td>In directer room tv legging ieesu solve.</td><td></td></tr><tr><td>01-06-2023 11:23:32</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>31-05-2023 06:05:43</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>31-05-2023 02:05:22</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>30-05-2023 05:17:33</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	01-06-2023 01:40:46	ChandanYadav	Completed	In directer room tv legging ieesu solve.		01-06-2023 11:23:32	ChandanYadav	New		-	31-05-2023 06:05:43	ChandanYadav	New		-	31-05-2023 02:05:22	ChandanYadav	New		-	30-05-2023 05:17:33	ChandanYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																															
01-06-2023 01:40:46	ChandanYadav	Completed	In directer room tv legging ieesu solve.																																
01-06-2023 11:23:32	ChandanYadav	New		-																															
31-05-2023 06:05:43	ChandanYadav	New		-																															
31-05-2023 02:05:22	ChandanYadav	New		-																															
30-05-2023 05:17:33	ChandanYadav	New		-																															
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>30-05-2023 10:36:37</td><td>Siddhesh Chavan</td><td>one camera star light issue resoved and 2 camera required and HDMI extender required for site camera and all camera working OK</td></tr><tr><td>24-05-2023 10:49:39</td><td>PravinJagade</td><td>4 camera pole bracket install. 1 camera sift</td></tr></tbody></table>					Date Time	Technician Name	Remark	30-05-2023 10:36:37	Siddhesh Chavan	one camera star light issue resoved and 2 camera required and HDMI extender required for site camera and all camera working OK	24-05-2023 10:49:39	PravinJagade	4 camera pole bracket install. 1 camera sift																					
Date Time	Technician Name	Remark																																	
30-05-2023 10:36:37	Siddhesh Chavan	one camera star light issue resoved and 2 camera required and HDMI extender required for site camera and all camera working OK																																	
24-05-2023 10:49:39	PravinJagade	4 camera pole bracket install. 1 camera sift																																	