




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE7014																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9029999160																			
Technician Name :	Siddhesh Chavan		Technician Mobile :	8080922985																
Ticket Type :	Complain	Date & Time :	05-12-2022 11:01:29																	
Vendor Details :																				
Company Name/Client Name :	Imprint Constructions Pvt Ltd	Customer's Mobile :	9029999160	Name :	Sahil Malik Bhai															
Address :																				
mumbai , , , 400067 , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	Repaired Bullet camera need to install and stand by camera ned to collect also 2 camera off issue need to check																			
Technician Comment :	2 bullet camera cable break need to change cable																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	2 bullet camera cable break need to change cable																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>05-12-2022 12:07:42</td><td>Siddhesh Chavan</td><td>Completed</td><td>2 bullet camera cable break need to change cable</td><td></td></tr><tr><td>05-12-2022 11:01:38</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	05-12-2022 12:07:42	Siddhesh Chavan	Completed	2 bullet camera cable break need to change cable		05-12-2022 11:01:38	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																
05-12-2022 12:07:42	Siddhesh Chavan	Completed	2 bullet camera cable break need to change cable																	
05-12-2022 11:01:38	Siddhesh Chavan	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>02-12-2022 10:38:45</td><td>Ravi Rajbhar</td><td>one camera canteen back side remove to client side confrim to shiva sir with cable epbax system check all ok 1. demo flat one ex.working 2. security cabin main gate ok working 3. canteen one ex. ok working 4. container 1 two ex. but no phone 5. container 2 two phone ok working 6.container 3 two line ok but one phone used codilate phone</td></tr><tr><td>21-11-2022 10:40:55</td><td>MayurYadav</td><td>2 camera shifting and one camera cable 15 mtrs return to back and second camera cable 20 mtrs back and third camera cable 50 mtrs return to back and 4 cameras angle set - 1 camera work pending due to pole not ready</td></tr></tbody></table>					Date Time	Technician Name	Remark	02-12-2022 10:38:45	Ravi Rajbhar	one camera canteen back side remove to client side confrim to shiva sir with cable epbax system check all ok 1. demo flat one ex.working 2. security cabin main gate ok working 3. canteen one ex. ok working 4. container 1 two ex. but no phone 5. container 2 two phone ok working 6.container 3 two line ok but one phone used codilate phone	21-11-2022 10:40:55	MayurYadav	2 camera shifting and one camera cable 15 mtrs return to back and second camera cable 20 mtrs back and third camera cable 50 mtrs return to back and 4 cameras angle set - 1 camera work pending due to pole not ready						
Date Time	Technician Name	Remark																		
02-12-2022 10:38:45	Ravi Rajbhar	one camera canteen back side remove to client side confrim to shiva sir with cable epbax system check all ok 1. demo flat one ex.working 2. security cabin main gate ok working 3. canteen one ex. ok working 4. container 1 two ex. but no phone 5. container 2 two phone ok working 6.container 3 two line ok but one phone used codilate phone																		
21-11-2022 10:40:55	MayurYadav	2 camera shifting and one camera cable 15 mtrs return to back and second camera cable 20 mtrs back and third camera cable 50 mtrs return to back and 4 cameras angle set - 1 camera work pending due to pole not ready																		