

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE2616																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9930088244																								
Technician Name :	Mayur Yadav	Technician Mobile :	8411951301																						
Ticket Type :	Complain	Date & Time :	25-01-2021 02:03:36																						
Vendor Details :																									
Company Name/Client Name :	Electromech Fire Fighters Pvt Ltd	Customer's Mobile :	9930088244	Name :	Sailesh Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	intrusion																								
Complain :	false alarm in 2 cabins																								
Technician Comment :	2motion sensor temp. issue solve hooter not sound battery low																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	2motion sensor temp. issue solve hooter not sound battery low																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>25-01-2021 08:01:49</td><td>MayurYadav</td><td>Work Pending</td><td>2motion sensor temp. issue solve hooter not sound battery low</td><td></td></tr><tr><td>25-01-2021 02:04:18</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>25-01-2021 02:03:36</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	25-01-2021 08:01:49	MayurYadav	Work Pending	2motion sensor temp. issue solve hooter not sound battery low		25-01-2021 02:04:18	MayurYadav	New		-	25-01-2021 02:03:36	MayurYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																					
25-01-2021 08:01:49	MayurYadav	Work Pending	2motion sensor temp. issue solve hooter not sound battery low																						
25-01-2021 02:04:18	MayurYadav	New		-																					
25-01-2021 02:03:36	MayurYadav	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>06-10-2020 10:45:54</td><td>RishiDesai</td><td>changed battery for manoj sir cabin now under observation rest checked system all working fine</td></tr><tr><td>25-09-2020 10:32:37</td><td>YashDoshi</td><td>check all system siren battery low and all sensor check working ok. in keypad of jablotron some liquid form as sanetizer so not coming display.</td></tr></tbody></table>					Date Time	Technician Name	Remark	06-10-2020 10:45:54	RishiDesai	changed battery for manoj sir cabin now under observation rest checked system all working fine	25-09-2020 10:32:37	YashDoshi	check all system siren battery low and all sensor check working ok. in keypad of jablotron some liquid form as sanetizer so not coming display.											
Date Time	Technician Name	Remark																							
06-10-2020 10:45:54	RishiDesai	changed battery for manoj sir cabin now under observation rest checked system all working fine																							
25-09-2020 10:32:37	YashDoshi	check all system siren battery low and all sensor check working ok. in keypad of jablotron some liquid form as sanetizer so not coming display.																							