Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Det	ails : VE8011							
Priority:	Low							
Created By:	Admin - Apurva Vajaria							
Complaint Mob.	0226128888							
Technician Name	Ravi Rajbhar			echn Iobil	nician 8080922965 le:			
Ticket Type:	AMC visiting	Date & Time	e: 0	01-04-2023 11:46:38				
Vendor Details :								
Company Name/Client Name :	Prime Civil Infrastructure Pvt Ltd	Customer's Mobile :	О	0226128888		Name :	Samidha Madam	
Address:								
Mumbai,,,, Maharashtra								
AMC Details :								
Expiry Date :	01-01-1970 05:30:00			ype:	pe:			
Product Name:	Ppm							
Complain:	need to do ppm cctv and 3 camera no Video issue							
Technician Comment :	ppm done off cctv camera and all ok working done and 3 camera no video issue resolved bcz power supply issue then power supply change and ok working done faulty power supply remove and take to office confrim to ekta mdm							
Complain Operator :	Desktop - Apurva Vajaria							
Remark :	ppm done off cctv camera and all ok working done and 3 camera no video issue resolved bcz power supply issue then power supply change and ok working done faulty power supply remove and take to office confrim to ekta mdm							
Status History :	Date Time	Technician Name	Statu	Status		emark		Sign
	01-04-2023 01:15:12	Ravi Rajbhar	Complet	ted	ppm done off cctv camera and all ok working done and 3 camera no video issue resolved bcz power supply issue then power supply change and ok working done faulty power supply remove and take to office confrim to ekta mdm		0	G alvall
	01-04-2023 11:46:46	Ravi Rajbhar	New					-
Previous	Date Time	Technician Nan	ne	Remark				
Complain History :	29-03-2023 10:43:52 Sonu Kumai			4 camera off issue power all camera working ok		supply faulty power supply change		
	06-03-2023 10:01:19 Atique Salmani There is issue in tv port need to changed new tv and then recheck.							nd then