




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE5330</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9167359050																								
<b>Technician Name :</b>	Siddhesh Chavan		<b>Technician Mobile :</b>	8080922985																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	30-04-2022 09:54:17																						
<b>Vendor Details :</b>																									
<b>Company Name/Client Name :</b>	Bombay Deying And Manufacturing Co. Ltd	<b>Customer's Mobile :</b>	9167359050	<b>Name :</b>	Sandeep Sir																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
<b>Expiry Date :</b>	31-07-2020 12:00:00		<b>Type :</b>	Comprehensive																					
<b>Product Name :</b>	Ppm																								
<b>Complain :</b>	cctv																								
<b>Technician Comment :</b>	cctv ppm done 1) one bullet camera need to change location HRC exit ground 50 MTR camera pinkish issue and 2 dome camera pinkish issue																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	cctv ppm done 1) one bullet camera need to change location HRC exit ground 50 MTR camera pinkish issue and 2 dome camera pinkish issue																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>30-04-2022 12:45:11</td><td>Siddhesh Chavan</td><td>Completed</td><td>cctv ppm done 1) one bullet camera need to change location HRC exit ground 50 MTR camera pinkish issue and 2 dome camera pinkish issue</td><td></td></tr><tr><td>30-04-2022 09:54:36</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>30-04-2022 09:54:17</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	30-04-2022 12:45:11	Siddhesh Chavan	Completed	cctv ppm done 1) one bullet camera need to change location HRC exit ground 50 MTR camera pinkish issue and 2 dome camera pinkish issue		30-04-2022 09:54:36	Siddhesh Chavan	New		-	30-04-2022 09:54:17	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																					
30-04-2022 12:45:11	Siddhesh Chavan	Completed	cctv ppm done 1) one bullet camera need to change location HRC exit ground 50 MTR camera pinkish issue and 2 dome camera pinkish issue																						
30-04-2022 09:54:36	Siddhesh Chavan	New		-																					
30-04-2022 09:54:17	Siddhesh Chavan	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>30-03-2022 09:59:56</td><td>Atique Salmani</td><td>Total 8 door access Second floor 1 door access Ground floor 2 door access Chairman confrence room door not realising by exit swich need to recheck becz chairman is there no permission for work Ground floor vip lift area SMPS faulty need to changed</td></tr><tr><td>15-03-2022 11:15:29</td><td>Prashant Nikalje</td><td>power supply on All door lock work but same access device not working need to check cabling and device .-</td></tr></tbody></table>					Date Time	Technician Name	Remark	30-03-2022 09:59:56	Atique Salmani	Total 8 door access Second floor 1 door access Ground floor 2 door access Chairman confrence room door not realising by exit swich need to recheck becz chairman is there no permission for work Ground floor vip lift area SMPS faulty need to changed	15-03-2022 11:15:29	Prashant Nikalje	power supply on All door lock work but same access device not working need to check cabling and device .-											
Date Time	Technician Name	Remark																							
30-03-2022 09:59:56	Atique Salmani	Total 8 door access Second floor 1 door access Ground floor 2 door access Chairman confrence room door not realising by exit swich need to recheck becz chairman is there no permission for work Ground floor vip lift area SMPS faulty need to changed																							
15-03-2022 11:15:29	Prashant Nikalje	power supply on All door lock work but same access device not working need to check cabling and device .-																							