Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 Support : | **W** : www.vallabhenterprises.com **E** : vallabhsecure@yahoo.co.in

Service Status Details : VE9396 Low **Priority** : **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9821745351 **No. : Technician** Ravi Rajbhar **Technician Mobile** 8080922965 Name : Date & Time : 02-09-2023 04:42:04 **Ticket Type :** AMC visiting **Vendor Details :** Mehta Kunj - Rite Customer's Mobile 9821745351 Sanjeev Sir Company Name : Name/Client Developers Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** Intercom Intercom PPM need to do **Complain**: 401 line ok working instument issue phone need to change client side 402 intercom issue Technician resloved and ok working done 302 line ok instument issue 104 out going call issue resloved and **Comment**: ok working done Complain Desktop - Apurva Vajaria **Operator** : **Remark** : 401 line ok working instument issue phone need to change client side 402 intercom issue resloved and ok working done 302 line ok instument issue 104 out going call issue resloved and ok working done **Status History :** Technician Date Time Status Sign Remark Name 04-09-2023 Ravi Rajbhar Completed 401 line ok working instument 05:41:09 issue phone need to change client side 402 intercom issue resloved and ok working done 302 line ok instument issue 104 out going call issue resloved and ok working done 04-09-2023 Ravi Rajbhar New 10:34:57 02-09-2023 Ravi Rajbhar Work Pending flat no 101/102 no intercom and 05:55:27 104 flat to security not ring call and flat no 302line issue and flat no 401 not ring call and 402 flat to security not ring call 02-09-2023 Ravi Rajbhar New 04:42:10

Previous Complain	Date Time	Technician Name	Remark
History :	12-05-2023 03:27:21	Kalpesh SubhashGurav	PPM Done
	21-03-2023 03:45:00	Sonu Kumar	99 intercom issue resolved working ok and 402intercom issue resolved working ok and intercom 100 line ok instrument speaker issue