Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE9872 Low **Priority** : **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 7798321220 **No. :** Technician Atique Salmani **Technician Mobile** 8080922984 Name : Complain Date & Time : 19-10-2023 05:49:48 **Ticket Type :** Vendor Details : Armstrong (India) Customer's 7798321220 Sanket Sir Company Name : Constructions Name/Client Name Mobile : Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** CCTV **Complain**: 1 camera no video issue Checked from camera end power ok but ohms not getting so checked from dvr end Bnc was not **Technician** connect proper so connect this properly working ok. Also reset date n time **Comment**: Complain Desktop - Apurva Vajaria **Operator** : **Remark** : Checked from camera end power ok but ohms not getting so checked from dvr end Bnc was not connect proper so connect this properly working ok. Also reset date n time **Status History : Date Time Technician Name** Status Remark Sign Atique Salmani 01-11-2023 03:59:38 Closed 20-10-2023 11:33:18 Atique Salmani Completed Checked from camera end power ok but ohms not getting so checked from dvr end Bnc was not connect proper so connect this properly working ok. Also reset date n time 19-10-2023 05:49:57 Atique Salmani New **Previous Date Time Technician Name** Remark Complain 28-10-2023 **History** : Atique Salmani 9 number camera godawun camera cable faulty cable approx rj 11:45:45 $6\ 200\ meter$ and $1\bar{4}\ number\ camera\ power\ looping\ rejoint$ working ok.alsonone camera angel set .also cmoss battery need to chenged 13-09-2023 DilshadKhan Intercom dressing done and 3 line issu line location Perception 01:25:12 and staff room and rest room resolved and solve and staff room ka phone not working all line ok