







# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE8972</b>																														
<b>Priority :</b>	Low																													
<b>Created By :</b>	Admin - Apurva Vajaria																													
<b>Complaint Mob. No. :</b>	9619838454																													
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984																										
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	25-07-2023 05:35:08																											
<b>Vendor Details :</b>																														
<b>Company Name/Client Name :</b>	Tavishh Designs	<b>Customer's Mobile :</b>	9619838454	<b>Name :</b>	Satya Sir																									
<b>Address :</b>																														
Mumbai , , , , Maharashtra																														
<b>AMC Details :</b>																														
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>																											
<b>Product Name :</b>	Access																													
<b>Complain :</b>	finger and card need to add and switch connection need to do																													
<b>Technician Comment :</b>	Sales head door not opening from exit switch Becz connection remooved due to some work so reconnection and working ok.																													
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																													
<b>Remark :</b>	Sales head door not opening from exit switch Becz connection remooved due to some work so reconnection and working ok.																													
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>27-07-2023 10:43:17</td><td>Atique Salmani</td><td>Completed</td><td>Sales head door not opening from exit switch Becz connection remooved due to some work so reconnection and working ok.</td><td></td></tr><tr><td>27-07-2023 10:12:05</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>25-07-2023 08:18:38</td><td>Atique Salmani</td><td>Work Pending</td><td>7 employee fingers add 2/2 finger thumbs and index And 5 card add and hand over to client Ess software installation done one door exit switch before compalin painding .</td><td></td></tr><tr><td>25-07-2023 05:35:15</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	27-07-2023 10:43:17	Atique Salmani	Completed	Sales head door not opening from exit switch Becz connection remooved due to some work so reconnection and working ok.		27-07-2023 10:12:05	Atique Salmani	New		-	25-07-2023 08:18:38	Atique Salmani	Work Pending	7 employee fingers add 2/2 finger thumbs and index And 5 card add and hand over to client Ess software installation done one door exit switch before compalin painding .		25-07-2023 05:35:15	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																										
27-07-2023 10:43:17	Atique Salmani	Completed	Sales head door not opening from exit switch Becz connection remooved due to some work so reconnection and working ok.																											
27-07-2023 10:12:05	Atique Salmani	New		-																										
25-07-2023 08:18:38	Atique Salmani	Work Pending	7 employee fingers add 2/2 finger thumbs and index And 5 card add and hand over to client Ess software installation done one door exit switch before compalin painding .																											
25-07-2023 05:35:15	Atique Salmani	New		-																										
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody></tbody></table>					Date Time	Technician Name	Remark																						
Date Time	Technician Name	Remark																												