

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE3780																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9049503080																								
Technician Name :	Mayur Yadav		Technician Mobile :	8411951301																					
Ticket Type :	Complain	Date & Time :	04-09-2021 10:20:30																						
Vendor Details :																									
Company Name/Client Name :	ALLIANZ TECHNOLOGY SE(PHASE I)	Customer's Mobile :	9049503080	Name :	Satyam Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	30-10-2020 12:00:00		Type :	Comprehensive																					
Product Name :	Ppm																								
Complain :	CCTV/FAS/PA/IAS/Fire Extinguisher																								
Technician Comment :	all cctv clean recording check hdd normal angle setting done .all working ok IAS System check alarm working ok FAS system check detector clean MCP check working ok camera angle setting done beam detector problem solve under observation.																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	all cctv clean recording check hdd normal angle setting done .all working ok IAS System check alarm working ok FAS system check detector clean MCP check working ok camera angle setting done beam detector problem solve under observation.																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>05-09-2021 03:40:48</td><td>MayurYadav</td><td>Completed</td><td>all cctv clean recording check hdd normal angle setting done .all working ok IAS System check alarm working ok FAS system check detector clean MCP check working ok camera angle setting done beam detector problem solve under observation.</td><td></td></tr><tr><td>04-09-2021 10:20:44</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>04-09-2021 10:20:30</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	05-09-2021 03:40:48	MayurYadav	Completed	all cctv clean recording check hdd normal angle setting done .all working ok IAS System check alarm working ok FAS system check detector clean MCP check working ok camera angle setting done beam detector problem solve under observation.		04-09-2021 10:20:44	MayurYadav	New		-	04-09-2021 10:20:30	MayurYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																					
05-09-2021 03:40:48	MayurYadav	Completed	all cctv clean recording check hdd normal angle setting done .all working ok IAS System check alarm working ok FAS system check detector clean MCP check working ok camera angle setting done beam detector problem solve under observation.																						
04-09-2021 10:20:44	MayurYadav	New		-																					
04-09-2021 10:20:30	MayurYadav	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>07-08-2023 12:36:53</td><td>PravinJagade</td><td></td></tr><tr><td>10-06-2023 11:34:43</td><td>Siddhesh Chavan</td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	07-08-2023 12:36:53	PravinJagade		10-06-2023 11:34:43	Siddhesh Chavan												
Date Time	Technician Name	Remark																							
07-08-2023 12:36:53	PravinJagade																								
10-06-2023 11:34:43	Siddhesh Chavan																								