




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE1401																																			
Priority :	High																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	9821122076																																		
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																															
Ticket Type :	Complain	Date & Time :	19-03-2020 09:57:00																																
Vendor Details :																																			
Company Name/Client Name :	Sharad Sir - Office	Customer's Mobile :	9821122076	Name :	Sharad Sir																														
Address :																																			
Mumbai , , , 400004 , Maharashtra																																			
AMC Details :																																			
Expiry Date :	01-01-1970 05:30:00		Type :																																
Product Name :	CCTV																																		
Complain :	CCTV ONLINE ISSUE & MAIN DOOR LOCK ISSUE																																		
Technician Comment :	cale need to do 20 mtr 2 core																																		
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :	cale need to do 20 mtr 2 core																																		
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>24-10-2020 10:18:53</td><td>Atique Salmani</td><td>Completed</td><td>cale need to do 20 mtr 2 core</td><td></td></tr><tr><td>19-03-2020 06:11:07</td><td>Atique Salmani</td><td>Work Pending</td><td>sharad sir door lock issue becoz smps to lock 10 mtr cable 2core faulty need to changed</td><td></td></tr><tr><td>19-03-2020 09:59:28</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>19-03-2020 09:57:19</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>19-03-2020 09:57:00</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	24-10-2020 10:18:53	Atique Salmani	Completed	cale need to do 20 mtr 2 core		19-03-2020 06:11:07	Atique Salmani	Work Pending	sharad sir door lock issue becoz smps to lock 10 mtr cable 2core faulty need to changed		19-03-2020 09:59:28	Atique Salmani	New		-	19-03-2020 09:57:19	Atique Salmani	New		-	19-03-2020 09:57:00	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																															
24-10-2020 10:18:53	Atique Salmani	Completed	cale need to do 20 mtr 2 core																																
19-03-2020 06:11:07	Atique Salmani	Work Pending	sharad sir door lock issue becoz smps to lock 10 mtr cable 2core faulty need to changed																																
19-03-2020 09:59:28	Atique Salmani	New		-																															
19-03-2020 09:57:19	Atique Salmani	New		-																															
19-03-2020 09:57:00	Atique Salmani	New		-																															
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>28-09-2022 12:03:17</td><td>Siddhesh Chavan</td><td>lock side cable breck re joined cable and lock issue resolved and need to change cable and vdp working ok</td></tr><tr><td>26-03-2022 02:35:08</td><td>YogeshDesai</td><td>one new bullet camera installed working ok . can be viewed on mobile software.and on screen.</td></tr></tbody></table>					Date Time	Technician Name	Remark	28-09-2022 12:03:17	Siddhesh Chavan	lock side cable breck re joined cable and lock issue resolved and need to change cable and vdp working ok	26-03-2022 02:35:08	YogeshDesai	one new bullet camera installed working ok . can be viewed on mobile software.and on screen.																					
Date Time	Technician Name	Remark																																	
28-09-2022 12:03:17	Siddhesh Chavan	lock side cable breck re joined cable and lock issue resolved and need to change cable and vdp working ok																																	
26-03-2022 02:35:08	YogeshDesai	one new bullet camera installed working ok . can be viewed on mobile software.and on screen.																																	