## Vallabh Enterprises

**Regd. Office** : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE6468 Low **Priority** : **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9821122076 **No. : Technician Name** Siddhesh Chavan **Technician Mobile** 8080922985 Complain Date & Time : 28-09-2022 12:03:17 **Ticket Type : Vendor Details :** 9821122076 Sharad Sir -Customer's Mobile Name : Sharad Sir Company Name/Client Name : Office Address : Mumbai,,,400004, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** CCTV **Complain**: lock is not getting operated used with vdp Technician lock side cable breck re joined cable and lock issue resolved and need to change cable and vdp working ok **Comment** : Complain Desktop - Apurva Vajaria **Operator** : **Remark** : lock side cable breck re joined cable and lock issue resolved and need to change cable and vdp working ok **Status History : Date Time Technician Name** Status Remark Sign 28-09-2022 05:20:49 Siddhesh Chavan Completed lock side cable breck re joined cable and lock issue resolved and need to change cable and vdp working ok 28-09-2022 12:03:32 Siddhesh Chavan New 28-09-2022 12:03:17 Siddhesh Chavan New **Previous Date Time Technician Name** Remark **Complain History** 26-03-2022 02:35:08 YogeshDesai one new bullet camera installed working ok . can be viewed on mobile software.and on screen. 27-09-2021 01:39:19 Neeraj Chauhan 11 mtr cabling done and use 1 power supply and DVr add mobile. lock working OK.