Vallabh Enterprises

 $\label{eq:conditional} \textbf{Regd. Office}: 401, shanti kutir, shivaji road, near thakur international school, kandivali (west) mumbai - 400067 \\ \text{Support}: | \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in}$

E: vallabhsecure@yahoo.co.in							
Service Status De	tails: VE6855						
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob.	28170556						
Technician Name :	Ravi Rajbhar		Technician :	chnician Mobile 8080922965			
Ticket Type :	Complain Date & Time :		16-11-2022 03:38:26				
Vendor Details :							
Company Name/Client Name :	Rahul Group Of Schools & College - HO	Customer's Mobile :	28170556		Name :	Shivani Madam	
Address:							
Mumbai , , , , Maharashtra							
AMC Details :							
Expiry Date :	01-01-1970 05:30:00		Type:	Type:			
Product Name:	CCTV						
Complain:	Need to do survey of CCTV						
Technician Comment :	3 camera check but one camera with cable faulty office in side and hondover jitu sir and two camera cable check and ok working done both side bnc pin change and ok working done with online done jitu sir phone						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	3 camera check but one camera with cable faulty office in side and hondover jitu sir and two camera cable check and ok working done both side bnc pin change and ok working done with online done jitu sir phone						
Status History:	Date Time	Technician Name	Status	Remark		Sign	
	24-11-2022 07:38:21	Ravi Rajbhar	Completed	3 camera check but one camera with cable faulty office in side and hondover jitu sir and two camera cable check and ok working done both side bnc pin change and ok working done with online done jitu sir phone			
	24-11-2022 02:25:14	ű	New			-	
	17-11-2022 12:38:38	ÿ	Work Pending			-	
	17-11-2022 12:36:48	ű	Cancelled			-	
	17-11-2022 11:54:15 16-11-2022 03:38:33	ű	New			-	
		J					

Previous Complain History:

Date Time	Technician Name	Remark
01-12-2022 10:56:31	Siddhesh Chavan	
29-11-2022 10:13:45	Siddhesh Chavan	install new 60 MTR extender and view working ok and one out side camera issue need to change camera