Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE6957 Low **Priority** : **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 28170556 **No. : Technician Name** Siddhesh Chavan **Technician Mobile** 8080922985 Complain 29-11-2022 10:13:45 **Ticket Type :** Date & Time : Vendor Details : Rahul Group Of Customer's Mobile 28170556 Shivani Company Name : Name/Client Name Schools & Madam College - HO Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** CCTV **Complain**: need to install hdmi extender 60 mtrs for rahul sir cabin viewing install new 60 MTR extender and view working ok and one out side camera issue need to Technician **Comment**: change camera Complain Desktop - Apurva Vajaria **Operator** : **Remark :** install new 60 MTR extender and view working ok and one out side camera issue need to change camera **Status History : Date Time Technician Name** Status Remark Sign 29-11-2022 01:09:39 Siddhesh Chavan Completed install new 60 MTR extender and view working ok and × one out side camera issue need to change camera 29-11-2022 10:13:58 Siddhesh Chavan New Previous **Date Time Technician Name** Remark **Complain History** 01-12-2022 10:56:31 Siddhesh Chavan 24-11-2022 03:42:57 Ravi Rajbhar sky link epbax system check total 23 line ok working done 3 mtnl line used but two line ok working and one line out side disturbance issue mtnl side then one line remove out side box confrim to sneha mdm (reception) and jitu sir Skylink epbax 8/48 line system