Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE7070 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 28170556 **No. :** Technician Siddhesh Chavan **Technician Mobile** 8080922985 Name : Complain 12-12-2022 11:16:32 **Ticket Type : Date & Time : Vendor Details :** Rahul Group Of Customer's Mobile 28170556 Company Name : Shivani Name/Client Schools & Madam College - HO Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** CCTV Chairman sir cabin 1 Camera getting on off on TV Ground floor office camera issue CCTV **Complain** : Dressing need to Do Technician 1) principal sir laptop install cp plus and guard station software install and viewing done 2) all dvr and NVR add to principal sir phone 3) ground floor cooler side dvr 14 no camera lock 4) **Comment**: software training done Complain Desktop - Apurva Vajaria **Operator** : **Remark** : 1) principal sir laptop install cp plus and guard station software install and viewing done 2) all dvr and NVR add to principal sir phone 3) ground floor cooler side dvr 14 no camera lock 4) software training done **Status History :** Date Time **Technician Name** Status Remark Sign 12-12-2022 Siddhesh Completed 1) principal sir laptop install cp 03:31:24 Chavan plus and guard station software install and viewing done 2) all dvr and NVR add to principal sir phone 3) ground floor cooler side dvr 14 no camera lock 4) software training done 12-12-2022 Siddhesh New 11:16:40 Chavan **Previous Date Time Technician Name** Remark Complain 01-12-2022 10:56:31 **History** : Siddhesh Chavan new hdmi extender install and tv working ok and tv side adapter not connected because power point not ready inform to jitu sir and old hdmi extender take to office install new 60 MTR extender and view working ok and one out 29-11-2022 10:13:45 Siddhesh Chavan side camera issue need to change camera