Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Details : VE7819									
Priority:	Low								
Created By:	Admin - Apurva Vajaria								
Complaint Mob.	28170556								
Technician Name :	Santosh Pathak			Technician 808092 Mobile :		080922980	2980		
Ticket Type :	Complain Date & Ti		lime :	10-03-2023 1	3 10:13:00				
Vendor Details :									
Company Name/Client Name :	Rahul Group Of Schools & : College - HO		r's Mobile	28170556		ame :	Shivani Madam		
Address:									
Mumbai,,,,Maharashtra									
AMC Details :									
Expiry Date :	01-01-1970 05:30:00			Type:					
Product Name:	CCTV								
Complain:	1 roadside camera is hanging issue								
Technician Comment :									
Complain Operator :	Desktop - Apurva Vajaria								
Remark:	Dilshad visited - 1 camera no video issue 1 rj45 connector used and 1 camera angle set resolution and solve								
Status History:	Date Time		Technician Name		Statu	ıs R	emark	Sign	
	20-03-2023 12:59:43		SantoshPathak		Complete	d		-	
	10-03-2023 10:13:22		SantoshPathak		New			-	
Previous Complain	Date Time Technicia		ian Name	n Name Remark					
History :	04-04-2023	Ravi Rajbhar		38, 36, ex. no. punching in cron with cable check 1st floor					
	10:05:08 23-03-2023 Ravi F		ihhar	staff room all ok working done and ex. no switch 24 rahul ho office skylink epbax system shifting done and 5					
	11:38:08	Tavi ru	<i>,</i>	new crown modul uesd and all ex. no. ok working done and 3 CO line connecte in system and in side 3 ex. no. pending client side bcz cable not drop to switch board total 20 line ok working done					